

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21007082/UPA3Q2
Date: 07/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900179059
Claimant Vehicle No :	SMS6919G	Insured Vehicle No :	SMP6853C
Date of Loss:	24/06/2021	Nature of Claim:	TP
		Claim No:	9687206301SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS6919G	Engine No:	L15B5573726
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11323689
Reg. Date:	10/03/2020 (Man. Year: 2019)	Odometer:	45846 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55Z R17	Rear Tyre Size:	215/55Z R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,411.56	4,953.36	8,458.20	63.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,190.00	1,610.00	42.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,211.56	7,143.36	10,068.20	58.50
Approved Total (Overridden) (S\$)		5,700.00		

Nett Amount (S\$)	17,211.56	5,700.00	11,511.56	66.88
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,336.45		
Global Sum Settlement (S\$)		6,300.00		

INSPECTION

Date of Assignment: 28/06/2021

Date Inspected: 28/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Zoom Autowerks Pte Ltd (HQ)
Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53,
Singapore 417808

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	995.20 FL	*588.20 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	136.40 FL	*- FL
3	2		*REAR BUMPER BRACKET	No such part	144.80 FL	*- FL
4	1		*REAR BUMPER REFLECTORS	N/S Cracked	291.60 FL	*145.40 FL
5	1		*REAR BUMPER SIDES	N/S Deformed / Twisted	391.60 FL	*195.80 FL
6	1		*REAR BUMPER CENTRE UNDER GARNISH	Torn	325.80 FL	*325.80 FL
7	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
8	1		*REAR TAILLAMPS	N/S Cracked	1,560.40 FL	*482.00 FL
9	1		*REAR TAILGATE	Badly Dented	1,228.90 FL	*997.30 FL
10	1		*REAR TAILGATE DAMPERS	Not Necessary	350.80 FL	*- FL
11	1		*REAR TAILGATE RUBBER	Twisted	215.30 FL	*166.20 FL
12	1		*REAR TAILGATE LOGO	Necessary	78.30 FL	*38.50 FL
13	1		*REAR TAILGATE EMBLEM (VEZEL)	Necessary	101.20 FL	*65.00 FL
14	1		*REAR TAILGATE GLASS	Not Necessary	1,285.70 FL	*- FL
15	1		*REAR TAILGATE GLASS INNER SPONGE SEAL /RUBBER	Necessary	175.40 FL	*175.40 FL
16	1		*REAR TAILGATE INNER TRIMBOARD	Deformed / Cracked	720.50 FL	*285.20 FL
17	1		*REAR TAILGATE INNER TRIMBOARD CLIPS	Necessary	60.00 FL	*60.00 FL
18	1		*REAR TAILGATE INNER LOCK	Bent	332.10 FL	*166.20 FL
19	1		*REAR TAILGATE INNER LOCK COVER	No such part	92.40 FL	*- FL
20	1		*REAR TAILGATE CENTRE GARNISH }	Cracked	387.30 FL	*226.70 FL
21	1		*REAR TAILGATE CENTRE CHROME GARNISH }		195.60 FL	*- FL
22	2		*REAR TAILGATE NUMBER PLATE LAMP	Not Necessary	97.20 FL	*- FL
23	1		*REAR TAILGATE LOCK KEYLESS SENSOR	Cracked	189.80 FL	*189.80 FL
24	1		*REAR TAILGATE REFLECTOR LAMP	N/S Cracked	1,140.60 FL	*380.50 FL
25	1		*REAR FENDER ARC-GARNISH	N/S Torn	396.40 FL	*198.20 FL
26	2		*REAR FENDER INNER SHIELD	Not Necessary	490.60 FL	*- FL
27	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
28	1		*REAR END PANEL	Badly Dented	759.10 FL	*575.30 FL
29	1		*REAR END PANEL TOP GARNISH	Twisted	175.90 FL	*175.90 FL
30	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
31	1		*REAR SPARE TYRE PANEL	Repair	926.30 FL	*- FL
32	1		*REAR SPARE TYRE PANEL SPONGE	Torn	341.80 FL	*341.80 FL
33	1		*REAR SPARE TYRE PANEL TOP BOARD	Serviceable	489.60 FL	*- FL
34	1		*REAR EXHAUST END BOX	Repair	745.60 FL	*- FL
35	2		*REAR EXHAUST END BOX MOUNTING	Not Necessary	96.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
37	1		*REAR SPARE TYRE PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
38	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
40	1		*REAR EXHAUST CHROME MUFFLER	Not Necessary	280.00 FS	*- FS
41	1		*REAR BUMPER TOP CENTRE GARNISH	Distorted	215.00 FS	*- FS
42	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	68.00 FS	*- FS
43	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,431.20	6,119.20
- List Item Discount on L Items 20.00/20.00% (S\$)	3,019.64	1,165.84
Total Parts (S\$)	13,411.56	4,953.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	1,000.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH	New	150.00	60.00
5	TO REMOVE & INSTALL REAR SPARE TYRE COMPONENTS ,TRIM & GARNISH	New	150.00	80.00
6	TO REMOVE & INSTALL REAR TAILGATE GLASS	New	150.00	120.00
7	TO RE-POSITION ,DRILL & INSTALL REVERSE SENSOR	New	150.00	50.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (\$\$)			3,800.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >