

TP ConPac.
Xiao Chen

FBL3195P · 2016 Sept.

Honda CBF190 184cc

LWBMC4692H1104197

Front Wheel Fender.	Cracked	121	/
Headlamp	Cut	480	/
Headlamp Bracket	NP HEC	45	X
Headlamp Cowling	XL R	210	X
Front Signal Lamp x02	RH cut	78 x 2 = 156	78.
Front Fork Assy.	cracked	785	/
Front Fork Underbracket	But	195	/
Steering Stem			
Steering Core and Bearing.	new	90(SN)	/
Fork Oil	} New	40(SN)	/
Fork oil Seal.		30(SN)	/

FBL3195P

Front Wing Mirror x 02 ^{LH} cut $65 \times 2 = 130$ ✓

Front Fairing Side x 02 ^{LH} cut $185 \times 2 = 370$ ¹⁸⁵

Slider LH cut $80(\text{SN})$ $70(\text{SN})$

Front LH Footrest Best 65 ✓

Balancer x 02 $35 \times 2 = 70$ X

Handle Bar x 02 $156 \times 2 = 312$ X

Rear Box cut $280(\text{SN})$ $250(\text{SN})$

Rear Box Bracket. Not m $180(\text{SN})$ X

Front Brake Disc Not m 290 X

Front Wheel Spindle Best 45 ✓

1899

S.N. 480

1709.10

FBL319SP.

Labour
Spray Painting.
Wiring.
Towing Fee

~~400~~ 200

~~400~~ 200

~~50~~ 30

40 ✓

670

Total: 2859.10

L/S: 2250

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: