

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21007090/UGS3Q2
Date: 15/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100444743
Claimant Vehicle No :	SMV1414M	Insured Vehicle No :	SCP8001A
Date of Loss:	27/06/2021	Nature of Claim:	TP
		Claim No:	5052339100SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV1414M	Engine No:	PE21291246
Make & Model:	MAZDA 6, 2.0 SEDAN EXECUTIVE 2WD (A)	Chassis No:	JM6GL1072K0320602
Reg. Date:	30/09/2020 (Man. Year: 2019)	Odometer:	15989 km
Colour:	Brown		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,405.53	1,249.36	156.17	11.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	985.00	420.00	565.00	57.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,390.53	1,669.36	721.17	30.17
+ GST 7.00/7.00% (S\$)	167.34	116.86	50.48	30.17

Nett Amount (S\$)	2,557.87	1,786.22	771.65	30.17
+ Loss of Use (1.0 x S\$90.00/day) (S\$)		90.00		
Nett Liability (S\$)		1,876.22		
Global Sum Settlement (S\$)		1,870.00		

INSPECTION

Date of Assignment: 28/06/2021

Date Inspected: 28/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Jin Auto Services Pte Ltd (Defu)
 Blk 14 Defu Lane 10, #01-410/412
 Singapore 539195

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,266.00 FL	*1,266.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
3	1		*REAR BUMPER LH TOW COVER	Missing	48.90 FL	*48.90 FL
4	1		*REAR REVERSE SENSOR	Shorted	180.60 FL	*180.60 FL
5	1		*REAR REVERSE SENSOR COVER	Cracked	18.20 FL	*18.20 FL
6	1		*REAR BUMPER REINFORCEMENT (NPA)	Repair	0.00 FL	*- FL
7	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
					Sub Total (\$)	1,561.70
					- List Item Discount on L Items 10.00/20.00% (\$)	156.17
					Total Parts (\$)	1,405.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	480.00	200.00
2	LABOUR CHARGE	New	480.00	200.00
3	WIRING	New	25.00	20.00
Gross Labour Cost (\$\$)			985.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >