

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007093/R1PS3Q2
Date: 23/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100223817
Claimant Vehicle No :	SHB8900U	Insured Vehicle No :	SGP7593S
Date of Loss:	27/06/2021	Nature of Claim:	TP
		Claim No:	0919062291SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8900U		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LELU496187
Reg. Date:	31/08/2020 (Man. Year: 2020)	Chassis No:	KMHC851CVLU211786
Colour:	Grey	Odometer:	36475 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,713.68	605.72	1,107.96	64.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	660.00	1,090.00	62.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,463.68	1,265.72	2,197.96	63.46
+ GST 7.00/7.00% (S\$)	242.46	88.60	153.86	63.46

Nett Amount (S\$)	3,706.14	1,354.32	2,351.82	63.46
<hr/>				
+ Car Rental (4.0 x S\$42.97/day) (S\$)		171.88		
+ Doc/Search Fee (S\$)		2.00		
<hr/>				
Nett Liability (S\$)		1,528.20		
<hr/>				
Global Sum Settlement (S\$)		1,500.00		
<hr/>				

INSPECTION

Date of Assignment: 28/06/2021

Date Inspected: 28/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	294.80 FL	*- FL
3	2		*REAR BUMPER REINFORCEMENT N/S & O/S LOWER BRACKET	Serviceable	30.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT CENTRE LOWER BRACKET	Serviceable	15.00 FL	*- FL
5	1		*LAMP ASSY -REAR FOG	Serviceable	201.50 FL	*- FL
6	2		*REAR BUMPER N/S & O/S STAY	Serviceable	276.20 FL	*- FL
7	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Serviceable	66.20 FL	*- FL
8	1		*MOULDING ASSY -REAR BUMPER CENTER	Scratched	216.50 FL	*216.50 FL
9	1		*REAR LICENCE LAMP ASSY	Serviceable	47.50 FL	*- FL
10	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
11	1		*SET REVERSE SENSOR	Serviceable	280.00 FS	*- FS
12	1		*REAR NUMBER PLATE WITH CASING	Cracked	50.00 FS	*35.00 FS
13	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
					<hr/>	
					Sub Total (S\$)	2,035.10
					- List Item Discount on L Items 20.00/20.00% (S\$)	321.42
					<hr/>	
					Total Parts (S\$)	1,713.68
					<hr/>	
					605.72	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	60.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO DISMANTLE ,VACUUM ,CLEAN UP ON THE TAIL GATE LOWER GLASS ,TO FIT UP TAIL GATE LOWER GLASS TO THE SAME	New	120.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE END PANEL ETC	New	650.00	300.00
5	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL,REAR BUMPER MOULDING CENTER	New	600.00	300.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
Gross Labour Cost (\$\$)			1,750.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >