

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	L INSURANCE (S) PL	R	ef:	CS/AGI21007095/Rqf3s2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	23/05/2022	
			С	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJQ 9412C	Veh. Inspected		SFM 7575Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10010665/JM	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		28/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	B.M.W. 328I GT 5DR SR	c.c		1997	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WBA3X32080D444577	Colour		WHITE	
	Odometer	171768 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/50 R18	PIRELLI		6 mm	
	L/H Front Tyre	225/50 R18	PIRELLI		6 mm	
	R/H Rear Tyre	225/50 R18	PIRELLI		6 mm	
	L/H Rear Tyre	225/50 R18	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	24/06/2021	Inspection Date		29/06/2021	
	Survey held at	56 LOYANG WAY #04-04				
	Repairer	AP AUTOMOTIVE SERVICES PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: