

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007096/T1VCN2**Date:** 21/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00013192100	
Claimant Vehicle No :	SFV8040U	Insured Vehicle No :	GBE6181X	
Date of Loss:	23/06/2021	Nature of Claim:	TP	Claim No: SNM21D203580/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFV8040U		Engine No:	L15B5571348
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)		Chassis No:	RU11321310
Reg. Date:	27/11/2019 (Man. Year: 2019)		Odometer:	25753 km
Colour:	Red			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,044.96	1,084.00	2,960.96	73.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,230.00	920.00	42.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,194.96	2,314.00	3,880.96	62.65
Approved Total (Overridden) (\$\$)		1,850.00		
(\$\$)	6,194.96	1,850.00	4,344.96	70.14
+ GST 7.00/7.00% (\$\$)	433.65	129.50	304.15	70.14
Nett Amount (\$\$)	6,628.61	1,979.50	4,649.11	70.14

INSPECTION

Date of Assignment:	28/06/2021	
Date Inspected:	29/06/2021 Inspected At:	Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFV8040U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE SKIRT ASSY	Not Necessary	334.10 FL	*- FL
2	1		*REAR BUMPER	Cut	1,161.50 FL	*588.20 FL
3	1		*REAR BUMPER REFLECTORS LH	Not Necessary	181.00 FL	*- FL
4	1		*REAR BUMPER SIDE GARNISH LH	Deformed	259.20 FL	*195.00 FL
5	1		*REAR BUMPER SIDE RETAINERS LH	Necessary	44.00 FL	*44.00 FL
6	1		*REAR BUMPER SIDE SPACER LH	Necessary	27.00 FL	*27.00 FL
7	1		*REAR FENDER INNER COWLING LH	Deformed	157.50 FL	*157.50 FL
8	1		*REAR FENDER INNER GARNISHES LH	Not Necessary	240.90 FL	*- FL
9	1		*REAR FENDER LH	Repair	982.80 FL	*- FL
10	1		*REAR LH DOOR PANEL	Repair	1,262.40 FL	*- FL
11	1		*REAR WHEEL ARCH GARNISH ASSY LH	Deformed	280.80 FL	*280.80 FL
12	1		*REAR BUMPER CLIPS (SET)	Necessary	50.00 FS	*30.00 FS
13	1		*REAR FENDER INNER CLIPS (SET)	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,031.20	1,342.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	986.24	258.50
Total Parts (\$\$)	4,044.96	1,084.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSE,REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	150.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
3	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE.BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
Gross Labour Cost (\$)			2,150.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >