

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21007098/AGA3Q2
Date: 05/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070016348-01
Claimant Vehicle No :	SMY2022M	Insured Vehicle No :	GBH1979D
Date of Loss:	26/06/2021	Nature of Claim:	TP
		Claim No:	8856354808SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY2022M	Engine No:	CZDC18584
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Chassis No:	WAUZZZF38M1042416
Reg. Date:	16/12/2020 (Man. Year: 2020)	Odometer:	10215 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,975.04	13,735.04	17,240.00	55.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,742.00	9,042.00	8,700.00	49.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	48,717.04	22,777.04	25,940.00	53.25
+ GST 7.00/7.00% (S\$)	3,410.19	1,594.39	1,815.80	53.25

Nett Amount (\$\$)	52,127.23	24,371.43	27,755.80	53.25
		+ Loss of Use (13.0 x S\$50.00/day) (\$\$)	650.00	
		+ Doc/Search Fee (\$\$)	2.00	
		Nett Liability (\$\$)	25,023.43	

INSPECTION

Date of Assignment: 01/07/2021

Date Inspected: 01/07/2021

Estimated Period of Repair: 12.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,815.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	414.00 FS	*- FS
3	2		*FRONT BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	177.00 FS	*- FS
4	1		*FRONT BUMPER TRIM	Deformed	356.00 FS	*284.40 FS
5	1		*FRONT BUMPER GRILLE -LOWER CENTRE	Not Necessary	217.00 FS	*- FS
6	2		*FRONT MOUNTING SENSOR -LH/RH	Not Necessary	317.00 FS	*- FS
7	1		*FRONT BUMPER GRILLE COVER -LOWER CENTRE	Not Necessary	51.00 FS	*- FS
8	1		*FRONT BUMPER LOWER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER	Not Necessary	763.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE -LH/RH	Not Necessary	306.00 FS	*- FS
11	2		*FRONT BUMPER AIR GUIDE TRIM -LH/RH	Not Necessary	328.00 FS	*- FS
12	1		*RADIATOR GRILLE	Cut	1,928.00 FS	*1,542.40 FS
13	1		*RADIATOR GRILLE BRACKET	Not Necessary	41.00 FS	*- FS
14	1		*RADIATOR SECURING PLATE	Not Necessary	33.00 FS	*- FS
15	1		*FRONT BUMPER CAMERA	Not Necessary	1,141.00 FS	*- FS
16	1		*RADIATOR GRILLE COVER	Cut	244.00 FS	*194.80 FS
17	1		*FRONT STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
18	2		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
19	4		*FRONT PARKING AID SEAL SENSOR	Not Necessary	14.00 FS	*- FS
20	1		*BONNET	Repair	3,508.00 FS	*- FS
21	1		*BONNET IMPACT PROTECTOR -CENTER	Not Necessary	28.00 FS	*- FS
22	2		*HEADLIGHT MOUNTING -LH/RH	Not Necessary	236.00 FS	*- FS
23	1		*REAR BUMPER	Deformed	1,634.00 FS	*1,307.20 FS
24	1		*REAR BUMPER SPOILER	Deformed	459.00 FS	*367.20 FS
25	2		*REAR BUMPER GRILLE -LH/RH	Not Necessary	304.00 FS	*- FS
26	1		*REAR BUMPER PARKING AID SENSOR SUPPORT RH	Not Necessary	25.00 FS	*- FS
27	2		*REAR BUMPER ADAPTER -LH/RH	Not Necessary	170.00 FS	*- FS
28	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	97.00 FS	*- FS
29	1		*REAR BUMPER BRACKET	Not Necessary	48.00 FS	*- FS
30	2		*REAR BUMPER REFLECTOR-LH/RH	Not Necessary	82.00 FS	*- FS
31	1		*REAR BOOT LID CONTROL UNIT	Not Necessary	411.00 FS	*- FS
32	1		*REAR BUMPER AERIAL	Not Necessary	71.00 FS	*- FS
33	1		*REAR SHOCK ABSORBER	Damaged	85.00 FS	*67.92 FS
34	1		*REAR BUMPER CARRIER	Dented	651.00 FS	*520.40 FS
35	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	58.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	126.00 FS	*- FS
37	2		*REAR BUMPER PARKING AID (NPA)	Not Necessary	0.00 FS	*- FS
38	4		*REAR BUMPER PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
39	1		*REAR BOOT LID	Dented	3,470.00 FS	*2,776.00 FS
40	1		*REAR BOOT LID ADHESIVE	Necessary	19.00 FS	*14.88 FS
41	4		*SELF LOCKING NUT -M6	Not Necessary	16.00 FS	*- FS
42	2		*REAR BOOTLID HINGE -LH/RH	Not Necessary	295.00 FS	*- FS
43	1		*REAR BOOTLID LOCK	Not Necessary	241.00 FS	*- FS
44	1		*REAR BOOTLID LOCK COVER	Not Necessary	13.00 FS	*- FS
45	1		*REAR LID STRIKER PLATE	Not Necessary	66.00 FS	*- FS
46	1		*REAR LID GASKET	Not Necessary	205.00 FS	*- FS
47	1		*REAR LID LOCK ACTUATOR	Damaged	1,389.00 FS	*1,111.20 FS
48	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
49	1		*Q3 EMBLEM	Necessary	99.00 FS	*79.04 FS
50	1		*REAR WINDOW	Necessary	958.00 FS	*766.00 FS
51	1		*PRIMER	Necessary	20.00 FS	*15.76 FS
52	2		*REAR WINDSCREEN SPOILER -LH/RH	Necessary	422.00 FS	*337.60 FS
53	1		*INNER REAR TAIL LIGHT -LH/RH	N/S Cut	1,852.00 FS	*740.40 FS
54	2		*REAR TAIL LIGHT TRIM -LH/RH	Not Necessary	60.00 FS	*- FS
55	2		*REAR LICENCE PLATE LIGHT	Damaged (1 PCS ONLY)	101.00 FS	*40.16 FS
56	2		*REAR WHEEL ARCH TRIM -LH/RH	Necessary	1,072.00 FS	*857.60 FS
57	2		*FRONT WHEEL ARCH TRIM -LH/RH	Necessary	1,072.00 FS	*857.60 FS
58	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
59	1		*REAR NO PLATE	Dented	60.00 FS	*60.00 FS
60	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
61	1		*SUNDRIES (3 PCS)	Necessary	350.00 FS	*18.64 FS
62	1		*REAR END PANEL -OUTER	Bent	337.52 FS	*337.52 FS
63	4		*REAR LID BUNGS	Necessary	93.52 FS	*93.52 FS
64	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
65	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
66	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
67	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **30,975.04** **13,735.04**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY & FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND BONNET ,RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
3	TO RESPRAY FRONT BUMPER ,FRONT BUMPER LOWER SPOILER ,BONNET AND BOTH FRONT WHEEL ARCH TRIMS	New	3,900.00	1,500.00
4	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION	New	360.00	360.00
5	TO REMOVE AND TRANSFER REAR LID S CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
6	TO RENEW REAR WINDSCREEN TO FACILITATE REAR LID RENEWAL	New	480.00	480.00
7	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN (BY OWNER)	New	190.00	190.00
8	TO CARRY OUT WATER SEEPAGE TEST ON REAR WINDSCREEN	New	200.00	150.00
9	TO DIMANTLE AND RENEW REAR BUMPER AND REAR LID TO REPAIR REAR END PANELLING REORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
10	TO RESPRAY REAR BUMPER ,REAR LID ,HINGES ,REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS	New	4,100.00	2,050.00
11	TO REAPPLY PAINT COATING ON AFFECTED AREA (BY OWNER)	New	180.00	180.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
13	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTETY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO COMPONENTS INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY	New	480.00	480.00
14	TO CUT OUT AND WELD REAR END PANELLING	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			17,742.00	9,042.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >