

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM21007102/Etce2	
	8 SHENTON WAY SINGAPORE 0688		Date:	05/07/2021		
	ATTN: ANG RICHA	RD		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 4313X	Veh. Inspected	l	FBL 7603C	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03CJQ	Excess (\$)		0.00	
	Assign From	ANG RICHARD	Assign Date		28/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA FZ16ST	c.c		153	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	ME145S094C2004723	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	60/70-17	DUNLOP		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	70/80-17	DUNLOP		5 mm	
	L/H Rear Tyre				mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.					
5. General Information						
	Accident Date	23/06/2021	Inspect Date /	Time	28/06/2021 (11:00 AM)	
	Survey held at	NO 1 BUKIT BATOK CRESCEN	Γ #02-58 WCEGA	PLAZA		
	Repairer	BIKERS AVENUE PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM21007102/Etce2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser