

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007104/URA3Q2
Date: 19/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210020055
Claimant Vehicle No :	SLE7511C	Insured Vehicle No :	SLK7924M
Date of Loss:	26/06/2021	Nature of Claim:	TP
		Claim No:	8275560174SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE7511C		
Make & Model:	MAZDA 5, 2.0 SP.6EAT SUNROOF (A)	Engine No:	PE10359461
Reg. Date:	29/07/2016 (Man. Year: 2016)	Chassis No:	JM6CW1071G0124126
Colour:	Red	Odometer:	107485 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,102.24	3,422.24	680.00	16.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,830.00	950.00	34.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,882.24	5,252.24	1,630.00	23.68
Approved Total (Overridden) (S\$)		3,650.00		

(S\$)	6,882.24	3,650.00	3,232.24	46.96
+ GST 7.00/7.00% (S\$)	481.76	255.50	226.26	46.97
Nett Amount (S\$)	7,364.00	3,905.50	3,458.50	46.96
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,507.50		

INSPECTION

Date of Assignment: 14/07/2021

Date Inspected: 14/07/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
 Singapore 489977

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE ABSORBER LH (NPA)	Not Necessary	0.00 FL	*- FL
2	1		*TAILGATE ABSORBER RH (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*TAIL GATE HINGE LH (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*TAIL GATE HINGE RH (NPA)	Not Necessary	0.00 FL	*- FL
5	1		*TAIL GATE WIPER MOTOR ASSEMBLY (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*TAIL GATE LOCK ASSEMBLY	Dented / Shorted	256.00 FL	*256.00 FL
7	1		*TAIL GATE INNER MOULDING (NPA)	Not Necessary	0.00 FL	*- FL
8	1		*TAIL GATE INNER TRIMBOARD (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*TAIL GATE EMBLEM	Necessary	44.00 FL	*44.00 FL
10	1		*TAIL GATE LOGO -MAZDA 5	Necessary	36.80 FL	*36.80 FL
11	1		*TAIL GATE LOGO -SKYACTIV	Necessary	54.00 FL	*54.00 FL
12	1		*TAIL GATE OUTER PANEL (NPA)	No such part	0.00 FL	*- FL
13	1		*TAIL LAMP LH (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*TAIL LAMP RH (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*TAIL GATE LAMP LH (NPA)	Not Necessary	0.00 FL	*- FL
16	1		*TAIL GATE LAMP RH (NPA)	Not Necessary	0.00 FL	*- FL
17	1		*REAR BUMPER	Dented	960.00 FL	*960.00 FL
18	1		*REAR BUMPER REFLECTOR LH (NPA)	Not Necessary	0.00 FL	*- FL
19	1		*REAR BUMPER REFLECTOR RH (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*END PANEL	Badly Dented	515.00 FL	*515.00 FL
21	1		*END PANEL TOP GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*SPARE TYRE TOP COVER ASSEMBLY (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*SPARE TYRE TANK SPONGE /TOOLS HOLDER (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*EXHAUST PIPE (NPA)	Not Necessary	0.00 FL	*- FL
25	1		*REAR NUMBER PLATE	Scratched	30.00 FS	*20.00 FS
26	1		*REAR NUMBER PLATE HOLDER	Scratched	30.00 FS	*20.00 FS
27	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
28	1		*SPARE TYRE	Not Necessary	380.00 FS	*- FS
29	1		*SPARE TYRE TANK (NPA)	Not Necessary	0.00 FS	*- FS
30	1		*SET REVERSE CAMERA	Shorted	580.00 FS	*380.00 FS
31	1		*TAILGATE }	Badly Dented	1,637.00 FL	*1,637.00 FL
32	1		*TAIL GATE OUTER GARNISH }		0.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)

4,802.80

4,122.80

- List Item Discount on L Items 20.00/20.00% (\$)

700.56

700.56

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$\$)	4,102.24
						3,422.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,200.00	800.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	900.00
3	ANTI-RUST COATING	New	150.00	60.00
4	WIRING	New	80.00	20.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (S\$)			2,780.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >