

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG20014293/R1VF3E2-1

**Date:** 22/07/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29083623QMX
<b>Claimant Vehicle No :</b>	SMP3879Z	<b>Insured Vehicle No :</b>	SJF7599T
Date of Loss:	19/12/2020	Nature of Claim:	TP
		Claim No:	632265

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMP3879Z</b>	Engine No:	1ZRY326536
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104556374
Reg. Date:	24/10/2016 (Man. Year: 2016)	Odometer:	54959 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,736.89	2,925.30	7,811.59	72.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,590.00	2,010.00	2,580.00	56.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,326.89</b>	<b>4,935.30</b>	<b>10,391.59</b>	<b>67.80</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,950.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,326.89</b>	<b>3,950.00</b>	<b>11,376.89</b>	<b>74.23</b>

### INSPECTION

Date of Assignment:	23/12/2020		
Date Inspected:	23/12/2020	Inspected At:	Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre Singapore 627603
Estimated Period of Repair:	8.0 days		

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2021)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMP3879Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	156.80 FL	*156.80 FL
2	1		*REAR BOOT LID	Repair	985.70 FL	*- FL
3	1		*REAR BOOT O/S LAMP	Damaged	288.70 FL	*288.70 FL
4	1		*REAR BOOT RUBBER	Not Necessary	145.70 FL	*- FL
5	1		*REAR BOOT COROLLA EMBLEM	Necessary	80.30 FL	*56.00 FL
6	1		*REAR BOOT ALTIS EMBLEM	Necessary	75.70 FL	*52.00 FL
7	1		*REAR O/S TAILLAMP	Damaged	380.10 FL	*380.10 FL
8	1		*REAR END PANEL	Repair	777.40 FL	*- FL
9	1		*REAR END PANEL INNER GARNISH	Serviceable	200.30 FL	*- FL
10	1		*REAR BUMPER	Damaged	588.70 FL	*588.70 FL
11	1		*REAR BUMPER O/S REFLECTOR	Damaged	60.10 FL	*60.10 FL
12	1		*REAR BUMPER REINFORCEMENT	Serviceable	344.70 FL	*- FL
13	1		*REAR BUMPER O/S SIDE RETAINER	Serviceable	65.00 FL	*- FL
14	2		*REAR BUMPER PDC SENSORS	Serviceable	390.00 FL	*- FL
15	1		*REAR SPARE TYRE PANEL	Serviceable	1,100.70 FL	*- FL
16	1		*REAR O/S FENDER	Damaged	1,120.70 FL	*987.00 FL
17	1		*REAR O/S FENDER INNER SHIELD	Serviceable	124.60 FL	*- FL
18	1		*REAR O/S WHEEL HUB WITH BEARING	Damaged	444.90 FL	*251.00 FL
19	1		*REAR O/S SHOCK ABSORBER	Serviceable	264.50 FL	*- FL
20	1		*REAR O/S AXLE BEAM	Serviceable	1,844.30 FL	*- FL
21	1		*ROCKER PANEL SIDE SKIRT	Not Necessary	498.66 FL	*- FL
22	1		*REAR O/S DOOR	Not Necessary	1,270.80 FL	*- FL
23	1		*REAR O/S DOOR WEATHERSTRIP	Not Necessary	267.50 FL	*- FL
24	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*REAR BUMPER LOWER SPOILER	Damaged	800.00 FS	*400.00 FS
27	1		*REAR O/S TYRE	Serviceable	400.00 FS	*- FS
28	1		*REAR O/S WHEEL RIM	Damaged	800.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,605.86</b>	<b>3,630.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,868.97	705.10
<b>Total Parts (\$\$)</b>	<b>10,736.89</b>	<b>2,925.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	60.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	0.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	150.00	0.00
7	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	200.00	40.00
8	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,800.00	800.00
9	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,800.00	900.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,590.00</b>	<b>2,010.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >