PAR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 64531173, Fax: 64536131. Consultants: Vehicle appraisal & inspection, accident investigation, expert witness

Report No: 0027-21-HLm

31 May 2021

Federal Components Pte Ltd c/o 160 Sin Ming Drive #05-17 Sin Ming Autocity Singapore 575722

INVOICE No.

0027-21-HLm

Vehicle No.

GBD3592T

S/NO.	SERVICES RENDERED	Amount due
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and	
	post repair inspection).	\$622.00
	Total amount payable	\$622.00

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy

R Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 64531173, Fax: 64536131. Consultants: Vehicle appraisal & inspection, accident investigation, expert witness

Report No: 0027-21-HLm

31 May 2021

ACCIDENT VEHICLE SURVEY REPORT

Federal Components Pte Ltd c/o 160 Sin Ming Drive #05-17 Sin Ming Autocity Singapore 575722

VEHICLE INFORMATION:

Vehicle Reg No .:

GBD3592T

Odometer:

142951km

Make & Model:

Nissan NV200 1.5L MT

Colour:

Silver

Chassis number:

VSKYBAM20Z0087621

Date of accident:

20/01/2021

Year of Regn.:

17/09/2014

Date inspected:

26/01/2021

Repairer at:

Hiap Lek Automobile Trading Date inspected (After Repair): 02/02/2021

160 Sin Ming Drive #05-17 Sin Ming Autocity

Singapore 575722

STATIC CHECKS, where applicable:

Steering:

serviceable

Footbrake:

serviceable

Handbrake:

serviceable

Paintwork:

Good

General condition:

Good

TIRE CONDITION:

LH / Make

RH / Make

Size

Front:

6mm/Linglong

6mm/Linglong

185R14

Rear:

6mm/Linglong

6mm/Linglong

185R14

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front LH portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Parts and Labour Assessment

Report No: 0027-21-HLm

Vehicle No: GBD3592T

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Front bonnet	1	buckled	858.50	858.50
Front bonnet insulator clip	5	necessary	17.50	17.50
Front grille	1	fractured	425.70	425.70
Front grille emblem 'Nissan' logo	1	necessary	33.10	33.10
Front head lamp lower apron panel LH	1	bent	348.80	348.80
Front bumper	1	deformed	512.20	512.20
Front bumper side retainer RH/LH	2	necessary	44.20	44.20
Front bumper sponge	1	deformed	116.23	116.23
Front bumper reinforcement		repair	386.20	0.00
Front suport panel		repair	295.70	0.00
Front fender LH	1	buckled	504.70	504.70
Front head lamp LH	1	broken	446.40	446.40
Front bumper fog lamp bracket LH		fractured	86.50	86.50
Front bumper fog lamp LH		fractured	220.00	220.00
Front fender inner shield RH	1	deformed	139.90	139.90
	Subt	otal before discount	4,435.63	3,753.73
Percentage discount 0%	and	10%	0.00	375.37
		Sub-total 1	4,435.63	3,378.36
Front bumper clip	10	necessary	35.00	35.00
Front fender inner shield clip RH	10	necessary	35.00	35.00
	Subt	otal before discount	70.00	70.00
Percentage discount 0%	and	0%	0.00	0.00
		Sub-total 2	70.00	70.00
		Parts-total	4,505.63	3,448.36
LABOUR1. To straighten and panel beating front support panel and frontLH frame members. To remove and refit above parts.				750.00
2. To putty, re-spray painting and polish affected areas.			1,200.00	880.00
3. To check and rectify wiring system.			80.00	50.00
4. To rust proof affected areas.			120.00	60.00
5. To reinstate artwork sticker on front bonnet.			200.00	200.00
		Labour total	2,500.00	1,940.00
	Pa	rts & Labour total	7,005.63	5,388.36

Annex A: Page 2 Report No: 0027-21-HLm-GBD3592T

PAR Automotive Consultancy

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :

\$4,300.00

and the recommended number of working days for the repairs is:

6

B J Loi (I Eng. MIMI, AIRTE) Automotive Appraiser