

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007118/BGA3Q2**Date:** 31/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210027272
Claimant Vehicle No :	SJK6204M	Insured Vehicle No :	GBD380H
Date of Loss:	25/06/2021	Nature of Claim:	TP
		Claim No:	3219050674SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK6204M	Engine No:	R18A1797130
Make & Model:	HONDA STREAM, 1.8 X (A)	Chassis No:	RN61087587
Reg. Date:	28/10/2008 (Man. Year: 2008)	Odometer:	165977 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,305.60	2,585.52	3,720.08	59.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,280.00	1,370.00	51.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,955.60	3,865.52	5,090.08	56.84
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	8,955.60	3,100.00	5,855.60	65.38
+ GST 7.00/7.00% (S\$)	626.89	217.00	409.89	65.38
Nett Amount (S\$)	9,582.49	3,317.00	6,265.49	65.38
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,804.45		
Global Sum Settlement (S\$)		3,800.00		

INSPECTION

Date of Assignment: 29/06/2021

Date Inspected: 29/06/2021 Inspected At:

Estimated Period of Repair: 4.0 days

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN MING
AUTOCITY
Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	683.40 FL	*- FL
2	1		*BONNET INNER LOCK	Not Damaged	110.00 FL	*- FL
3	2		*BONNET HINGE	Not Damaged	169.00 FL	*- FL
4	1		*FRONT BUMPER	Cut	786.50 FL	*655.40 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	136.00 FL	*49.40 FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	373.20 FL	*228.20 FL
7	1		*FRONT BUMPER LOWER GRILLE	Broken	289.70 FL	*123.00 FL
8	1		*FRONT BUMPER FOG LAMP GARNISH RH	Broken	186.30 FL	*47.90 FL
9	1		*FRONT GRILLE	Broken	211.80 FL	*211.80 FL
10	1		*FRONT GRILLE LOGO	Necessary	85.40 FL	*23.40 FL
11	1		*FRONT GRILLE EMBLEM	Not Damaged	268.40 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Not Damaged	658.60 FL	*- FL
13	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Damaged	184.30 FL	*- FL
14	1		*FRONT FENDER RH	Dented	582.60 FL	*582.60 FL
15	1		*FRONT FENDER INNER COWLING RH	Broken	142.00 FL	*142.00 FL
16	1		*HEADLAMP	O/S Broken	1,512.40 FL	*756.20 FL
17	2		*HEADLAMP LOWER BRACKET	Broken	187.00 FL	*187.00 FL
18	1		*WIPER WASHER TANK	Not Damaged	285.60 FL	*- FL
19	1		*WIPER WASHER TANK MOTOR	Not Damaged	142.30 FL	*- FL
20	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
21	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
22	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
24	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
25	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
26	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*FRONT FENDER SEALANT	Necessary	100.00 FS	*40.00 FS
28	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*20.00 FS
29	1		*FRONT NUMBER PLATE W/CASING	Cracked	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,704.50	3,186.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,398.90	601.38
Total Parts (\$\$)	6,305.60	2,585.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BONNET COMPONENT	New	150.00	80.00
2	UPHOLSTERY	New	200.00	0.00
3	CHECK WIRING	New	100.00	0.00
4	PANEL BEATING	New	1,000.00	600.00
5	RUST PROOFING	New	200.00	0.00
6	SPRAY PAINTING	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,650.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >