

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21007119/BQF3E2

Date: 13/08/2021

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|-----------------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | MSD/VMS/20-511757-WTT |
| Claimant Vehicle No : | SLW8705J | Insured Vehicle No : | FBM3043P |
| Date of Loss: | 26/06/2021 | Nature of Claim: | TP |
| | | Claim No: | MSC/V/21-000295 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SLW8705J | | |
| Make & Model: | MERCEDES-BENZ C180K, 1.6 (A) | Engine No: | 27191031343215 |
| Reg. Date: | 16/03/2011 (Man. Year: 2011) | Chassis No: | WDD2040452A512958 |
| Colour: | Silver | Odometer: | 107092 km |
| Engine Capacity: | 1597 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 235/35 R19 | Rear Tyre Size: | 235/35 R19 |
| Front Left Side: | Goodyear 6 mm | Rear Left Side: | Goodyear 6 mm |
| Front Right Side: | Goodyear 6 mm | Rear Right Side: | Goodyear 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|-----------------|--------------|
| Parts | 9,079.60 | 2,583.99 | 6,495.61 | 71.54 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,540.00 | 1,140.00 | 1,400.00 | 55.12 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 11,619.60 | 3,723.99 | 7,895.61 | 67.95 |
| Approved Total (Overridden) (S\$) | | 2,950.00 | | |
| (S\$) | 11,619.60 | 2,950.00 | 8,669.60 | 74.61 |
| + GST 7.00/7.00% (S\$) | 813.37 | 206.50 | 606.87 | 74.61 |
| Nett Amount (S\$) | 12,432.97 | 3,156.50 | 9,276.47 | 74.61 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 28/06/2021 | |
| Date Inspected: | 01/07/2021 Inspected At: | Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875 |
| Estimated Period of Repair: | 6.0 days | |

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 13 Aug 2021) |
| Parts: | 143 | MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLW8705J) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER (AMG) | Broken | 1,555.00 FL | *1,345.10 FL |
| 2 | 1 | | *REAR BUMPER RH SIDE BRACKET | Necessary | 98.00 FL | *56.00 FL |
| 3 | 1 | | *REAR BUMPER LH SIDE BRACKET | Necessary | 98.00 FL | *56.00 FL |
| 4 | 1 | | *REAR BUMPER CENTRE BRACKET | Not Damaged | 182.00 FL | *- FL |
| 5 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 675.00 FL | *675.00 FL |
| 6 | 1 | | *REAR BUMPER LOWER COVER | No such part | 168.00 FL | *- FL |
| 7 | 1 | | *RH TAILLAMP ASSY | No such part | 724.00 FL | *- FL |
| 8 | 1 | | *RH TAILLAMP SIDE GARNISH | Not Damaged | 115.00 FL | *- FL |
| 9 | 1 | | *END PANEL | Not Necessary | 1,180.00 FL | *- FL |
| 10 | 1 | | *END PANEL INNER GARNISH | Not Damaged | 158.00 FL | *- FL |
| 11 | 1 | | *BOOTLID | Not Damaged | 1,685.00 FL | *- FL |
| 12 | 1 | | *BOOTLID CENTRE EMBLEM | Not Necessary | 55.00 FL | *- FL |
| 13 | 1 | | *REAR RH FENDER INNER TRIM | Not Damaged | 311.00 FL | *- FL |
| 14 | 1 | | *REAR BUMPER LOWER GARNISH | Dislodged | 850.00 FS | *395.10 FS |
| 15 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 80.00 FS | *30.00 FS |
| 16 | 1 | | *SET REAR BUMPER REVERSE SENSOR (4 SENSORS) | Short Circuit | 450.00 FS | *200.00 FS |
| 17 | 1 | | *EXHAUST SILENCER ASSY | Not Necessary | 1,280.00 FS | *- FS |
| 18 | 1 | | *EXHAUST SILENCER GASKET | Not Necessary | 36.00 FS | *- FS |
| 19 | 1 | | *END PANEL JOINT SEALANT | Necessary | 80.00 FS | *40.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 9,780.00 | 2,797.20 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 700.40 | 213.21 |
| Total Parts (\$\$) | 9,079.60 | 2,583.99 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR CHARGE TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/WELD AND RE-ALIGN ALL AFFECTED PANEL | New | 900.00 | 600.00 |
| 2 | SPRAY PAINTING ON AFFECTED PANELS | New | 1,000.00 | 400.00 |
| 3 | CHECK WIRING AND LIGHTING SYSTEM | New | 80.00 | 0.00 |
| 4 | APPLY RUST COATING CHEMICAL ON AFFECTED PANELS | New | 60.00 | 0.00 |
| 5 | REMOVE AND REPLACE REAR INNER TRIMS, GARNISH AND BOARD TO ASSIST REPAIR | New | 200.00 | 80.00 |
| 6 | REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR (4 SENSORS) | New | 120.00 | 60.00 |
| 7 | REMOVE AND REPLACE EXHAUST SILENCER ASSY AND GASKET | New | 180.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 2,540.00 | 1,140.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >