

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007121/BVCN2**Date:** 13/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00115302003
Claimant Vehicle No :	YQ2680M	Insured Vehicle No :	GBF5475A
Date of Loss:	26/06/2021	Nature of Claim:	TP
		Claim No:	SNM21D203596/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ2680M		
Make & Model:	mitsubishi canter, 2.5 D FB510B (M)	Engine No:	4P10E17987
Reg. Date:	21/09/2020 (Man. Year: 2020)	Chassis No:	FEB21EA35063
Colour:	White	Odometer:	34034 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,134.35	5,779.20	9,355.15	61.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,600.00	3,900.00	2,700.00	40.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,734.35	9,679.20	12,055.15	55.47
Approved Total (Overridden) (\$\$)		7,750.00		
Nett Amount (\$\$)	21,734.35	7,750.00	13,984.35	64.34

INSPECTION

Date of Assignment:	29/06/2021		160 SIN MING DR
Date Inspected:	29/06/2021	Inspected At:	#01-14 SIN MING AUTO CITY
			SINGAPORE 575722
			REPAIRER: TEAM AUTOPRO PTE LTD
Estimated Period of Repair:	12.0 days		

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Sep 2021)	
Parts:	N/A	mitsubishi canter 2.5 D FB510B (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ2680M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP	O/s Broken	771.20 FL	*195.00 FL
2	1		*TAILLAMP BRACKET	O/s Bent	596.60 FL	*123.93 FL
3	1		*REAR NUMBER PLATE LAMP	Not Damaged	78.00 FL	*- FL
4	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
5	1		*REAR DOOR LH	Dented	2,100.00 FS	*1,200.00 FS
6	1		*REAR DOOR RH	Dented	2,100.00 FS	*1,200.00 FS
7	1		*REAR DOOR LOCK LH	Bent	650.00 FS	*300.00 FS
8	1		*REAR DOOR LOCK RH	Not Damaged	650.00 FS	*- FS
9	1		*REAR DOOR HINGE LH (2 Pcs)	Bent (1 Pc only)	600.00 FS	*200.00 FS
10	1		*REAR DOOR HINGE RH (2 Pcs)	Bent (1 Pc only)	600.00 FS	*200.00 FS
11	1		*REAR DOOR INNER BOARD LH	Dented	300.00 FS	*100.00 FS
12	1		*REAR DOOR INNER BOARD RH	Dented	300.00 FS	*100.00 FS
13	1		*REAR DOOR RIVETS LH	Necessary	100.00 FS	*30.00 FS
14	1		*REAR DOOR RIVETS RH	Not Necessary	100.00 FS	*- FS
15	1		*REAR DOOR PILLAR LH	Dented	1,800.00 FS	*800.00 FS
16	1		*REAR DOOR PILLAR RH	Dented	1,800.00 FS	*800.00 FS
17	1		*REAR DOOR PILLAR RIVETS RH	Necessary	100.00 FS	*30.00 FS
18	1		*REAR DOOR PILLAR RIVETS LH	Necessary	100.00 FS	*30.00 FS
19	1		*REAR DOOR ADVERTISEMENT (Kiv)	Necessary	1,000.00 FS	*- FS
20	1		*REAR DOOR STICKER 60KM/H	Necessary	40.00 FS	*20.00 FS
21	1		*REAR WONDER STEP BAR	Dented	450.00 FS	*200.00 FS
22	1		*REAR END PANEL	Dented	800.00 FS	*200.00 FS
23	1		*REAR NUMBER PLATE	Dented	80.00 FS	*30.00 FS
24	1		*REAR NUMBER PLATE BRACKET	Dented	300.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,495.80	5,858.93
- List Item Discount on L Items 25.00/25.00% (\$\$)	361.45	79.73
Total Parts (\$\$)	15,134.35	5,779.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REAR DOOR COMPONENT LH/RH	New	500.00	300.00
2	R&R REAR WOODENSTEP BAR	New	150.00	80.00
3	R&R REAR END PANEL	New	150.00	120.00
4	R&R CARGO BOX	New	1,200.00	800.00
5	UPHOLSTERY	New	300.00	0.00
6	CHECK WIRING	New	100.00	0.00
7	PANEL BEATING	New	2,000.00	1,000.00
8	RUST PROOFING	New	200.00	0.00
9	SPRAY PAINTING	New	2,000.00	1,600.00
Gross Labour Cost (S\$)			6,600.00	3,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >