

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21007124/AVCE2

Date: 29/09/2021

REFERENCE

Insured/Claimant:	RUTH AILEEN MAH SOOK FUN	Policy No:	1800089458	
Date of Loss:	23/06/2021	Nature of Claim:	OD	Claim No: 8232674333SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBV4188B		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK064960
Reg. Date:	27/07/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF5XJA116500
Colour:	Blue	Odometer:	37832 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$138,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,938.00	9,738.56	6,199.44	38.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,732.00	4,132.00	3,600.00	46.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,670.00	13,870.56	9,799.44	41.40
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	22,870.00	13,070.56	9,799.44	42.85
+ GST 7.00/7.00% (S\$)	1,600.90	914.94	685.96	42.85
Nett Amount (S\$)	24,470.90	13,985.50	10,485.40	42.85

INSPECTION

Date of Assignment:	29/06/2021		
Date Inspected:	28/06/2021	Inspected At:	24 BENOI SECTOR Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	228.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	63.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	474.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	36.00 FS	*28.72 FS
8	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
9	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
10	1		*AIR-CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
11	1		*FRONT FENDER - RH	Distorted	1,060.00 FS	*848.00 FS
12	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
13	1		*FRONT FENDER CLOSING ELEMENT - RH	Damaged	74.00 FS	*59.04 FS
14	1		*FRONT FENDER BRACKET - RH	Damaged	35.00 FS	*27.92 FS
15	1		*POP RIVERT (5PCS)	Necessary	17.00 FS	*15.84 FS
16	1		*FRONT FENDER BRACE - RH	Bent	118.00 FS	*94.40 FS
17	1		*FRONT FENDER BRACKET - RH	Not Necessary	49.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - RH	Not Necessary	35.00 FS	*- FS
19	1		*FRONT FENDER TRIM - RH	Necessary	164.00 FS	*130.80 FS
20	1		*FRONT WHEEL HOUSING LINER - RH	Torn	275.00 FS	*219.60 FS
21	1		*FRONT WHEEL SPOILER - RH	Cracked	73.00 FS	*58.40 FS
22	1		*FRONT WHEEL SPOILER TRIM - RH	Not Necessary	36.00 FS	*- FS
23	1		*FRONT FENDER FLEDGE COVER - RH	Not Necessary	16.00 FS	*- FS
24	1		*LED HEADLIGHT - RH	Cracked	7,902.00 FS	*6,321.60 FS
25	1		*LIFT CYLINDER - RH	Not Necessary	198.00 FS	*- FS
26	1		*FRONT ALUMINIUM RIM - RH	Repair	1,690.00 FS	*- FS
27	1		*SUNDRIES	Necessary	300.00 FS	*2.64 FS
28	1		*FRONT RHS DOOR CHROME TRIM (Supplementary)	Necessary	164.00 FS	*130.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,938.00 9,738.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILIATE RESPRAY OF RHS FRONT DOOR (Supplementary)	New	280.00	280.00
8	TO RESPRAY RHS FRONT DOOR (Supplementary)	New	1,200.00	550.00
Gross Labour Cost (\$\$)			7,732.00	4,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >