

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/GRB21007125/AEA3Q2
Date: 07/09/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMD8049H	Insured Vehicle No :	SLS9289H
Date of Loss:	28/06/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002800

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD8049H		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHG6520
Reg. Date:	05/09/2018 (Man. Year: 2018)	Chassis No:	MMBSTA13AJH003162
Colour:	White	Odometer:	66065 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,337.77	4,489.65	2,848.12	38.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,810.00	1,680.00	48.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,827.77	6,299.65	4,528.12	41.82
Approved Total (Overridden) (S\$)		5,000.00		

(S\$)	10,827.77	5,000.00	5,827.77	53.82
+ GST 7.00/7.00% (S\$)	757.94	350.00	407.94	53.82
Nett Amount (S\$)	11,585.71	5,350.00	6,235.71	53.82
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,897.45		

INSPECTION

Date of Assignment: 29/06/2021

Date Inspected: 29/06/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Mg Solution Pte Ltd - Kaki Bukit (HQ)
 25 Kaki Bukit Road 4 #04-01
 Singapore 41800

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Aug 2021)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD8049H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	950.50 FL	*828.00 FL
2	1		*BOOTLID LOGO	Necessary	62.20 FL	*62.20 FL
3	1		*BOOTLID EMBLEM ATTRAGE	Necessary	63.00 FL	*63.00 FL
4	1		*BOOTLID EMBLEM MIVEC TECHNOLOGY	Necessary	63.00 FL	*63.00 FL
5	1		*BOOTLID EMBLEM C&C	Necessary	63.00 FL	*63.00 FL
6	1		*BOOTLID TOP LOCK	Damaged	228.40 FL	*189.00 FL
7	1		*BOOTLID CATCH	Not Necessary	103.00 FL	*- FL
8	2		*BOOTLID HINGE	Not Necessary	246.40 FL	*- FL
9	1		*BOOTLID KEYLESS ANTENNA	Cracked	233.20 FL	*95.00 FL
10	1		*BOOTLID BUZZER	Cracked	203.40 FL	*91.00 FL
11	1		*BOOTLID WEATHERSTRIP	Cut	192.00 FL	*192.00 FL
12	1		*BOOTLID SENSOR LOCK	Not Necessary	203.40 FL	*- FL
13	1		*BOOTLID OUTER GARNISH CHROME	Cut	220.00 FL	*220.00 FL
14	1		*REAR BUMPER	Deformed	822.30 FL	*748.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	145.00 FL	*78.00 FL
16	1		*REAR BUMPER AIR VENT	Not Necessary	89.00 FL	*- FL
17	1		*REAR BUMPER AIR VENT COVER	Not Necessary	133.00 FL	*- FL
18	2		*REAR BUMPER REFLECTOR	Not Necessary	126.00 FL	*- FL
19	1		*SET REAR NUMBER PLATE LAMP	Not Necessary	133.80 FL	*- FL
20	1		*TAILLAMP	N/S Cracked	926.40 FL	*276.00 FL
21	2		*TAILLAMP PANEL	Not Necessary	348.00 FL	*- FL
22	1		*REAR END PANEL	Dented	566.30 FL	*566.30 FL
23	1		*REAR END PANEL TOP GARNISH	Deformed	174.00 FL	*174.00 FL
24	1		*REAR NUMBER PLATE	Dented	50.00 FS	*50.00 FS
25	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
26	1		*REAR BUMPER BODY KIT	Cracked	1,200.00 FS	*800.00 FS
27	1		*SET TAILLAMP CLIP	Necessary	20.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*TAILLAMP PANEL SEALANT	Not Necessary	20.00 FS	*- FS
29	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
30	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
31	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,967.30	4,860.50
- List Item Discount on L Items 10.00/10.00% (S\$)	629.53	370.85
Total Parts (S\$)	7,337.77	4,489.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	150.00	60.00
4	WIRING CHECK	New	150.00	50.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	150.00	50.00
7	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
Gross Labour Cost (S\$)			3,490.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >