



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M034PH

Date: 27th July 2021

Our Ref: CS3/ASM21003086/Gtf3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Tan Wan Cong

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMK 6892R
INSURED VEHICLE: SKT 2878k
ACCIDENT DATE: 05/03/2021**

We thank you for your instruction on 29/06/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMK 6892R from M/s Absolute Appraisal Services Pte Ltd.
- b) Singapore Accident Statement of Vehicles SMK 6892R and SKT 2878K.
- c) Police Report of Vehicles SMK 6892R
- d) Final Repair Bill of SMK 6892R from M/s MJE Motor.
- e) Colour damaged vehicle photographs of SMK 6892R.

Pre-Repair Inspection Date : 10/03/2021 at M/s MJE Motor, Blk 7 Sin Ming Ind Est Sec C #01-96, Singapore 575642.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMK 6892R
Make & Model	: Kia Cerato 1.6 (A) EX
Year of Registration	: 2019
Chassis Number	: KNAF3416MK5036735
Engine Capacity	: 1591 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.