

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21007127/ATCN2**Date:** 16/11/2021**REFERENCE**

Insured/Claimant:	LONG SEY HAI	Policy No:	2100462895	
Date of Loss:	24/06/2021	Nature of Claim:	OD	Claim No: 6494683547SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDA7242U		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD226388
Reg. Date:	27/04/2016 (Man. Year: 2015)	Chassis No:	WAUZZZ8U7GR068212
Colour:	Black	Odometer:	57323 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$83,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R17	Rear Tyre Size:	235/55R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,005.00	11,626.32	18,378.68	61.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,264.00	13,344.00	12,920.00	49.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	56,269.00	24,970.32	31,298.68	55.62
- Excess (S\$)	3,300.00	3,300.00	0.00	0.00
(S\$)	52,969.00	21,670.32	31,298.68	59.09
+ GST 7.00/7.00% (S\$)	3,707.83	1,516.92	2,190.91	59.09
Nett Amount (S\$)	56,676.83	23,187.24	33,489.59	59.09

INSPECTION

Date of Assignment:	29/06/2021	
Date Inspected:	28/06/2021	Inspected At: 24 BENOI SECTOR SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	13.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	2,125.00 FS	*1,700.00 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	109.00 FS	*- FS
3	1	*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	153.00 FS	*- FS
4	1	*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	176.00 FS	*- FS
5	1	*FRONT BUMPER SPOILER	Cut	581.00 FS	*464.40 FS
6	1	*FRONT FENDER-LH	Distorted	902.00 FS	*721.60 FS
7	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	70.00 FS	*- FS
8	1	*FRONT FENDER BRACKET-LH	Distorted	83.00 FS	*65.84 FS
9	1	*FRONT FENDER RIVET (6 Pcs)	Necessary	20.00 FS	*15.84 FS
10	1	*FRONT FENDER BRACE-LH	Bent	105.00 FS	*83.60 FS
11	1	*FRONT FENDER CLOSING ELEMENT-LH	Deformed	33.00 FS	*26.16 FS
12	1	*FRONT WHEEL HOUSING SEAL	Not Necessary	18.00 FS	*- FS
13	1	*FRONT WHEEL HOUSING LINER	Torn	240.00 FS	*191.60 FS
14	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	153.00 FS	*- FS
15	1	*FRONT WHEEL SPOILER-LH	Not Necessary	73.00 FS	*- FS
16	2	*FRONT WHEEL COVER-LH/RH	N/s Cut/O/s Necessary	1,056.00 FS	*844.00 FS
17	1	*FRONT FENDER UPPER BRACKET LH	Distorted	65.00 FS	*51.28 FS
18	1	*FRONT SIDE MEMBER	Repair	431.00 FS	*- FS
19	2	*SIDE MEMBER RIVETTED CAP	Necessary	6.00 FS	*4.80 FS
20	1	*HEADLIGHT MOUNTING-LH	Cracked	118.00 FS	*94.40 FS
21	1	*HEADLIGHT RETAINING PLATE-LH	Cracked	87.00 FS	*69.12 FS
22	1	*HEADLIGHT-LH	Cracked	7,781.00 FS	*6,224.80 FS
23	1	*HEADLIGHT LED MODULE	Not Necessary	781.00 FS	*- FS
24	1	*HEADLIGHT FAN	Not Necessary	398.00 FS	*- FS
25	1	*HEADLIGHT POWER MODULE-DAY LIGHT	Not Necessary	553.00 FS	*- FS
26	1	*HEADLIGHT POWER MODULE-MAIN LIGHT	Not Necessary	686.00 FS	*- FS
27	1	*HEADLIGHT POWER MODULE-CORNERING LIGHT	Not Necessary	557.00 FS	*- FS
28	1	*HEADLIGHT HOSE	Not Necessary	36.00 FS	*- FS
29	1	*WINDSHIELD MOLDING-LH	Damaged	67.00 FS	*53.44 FS
30	1	*FRONT COWL-SIDE SEAL-LH	Not Necessary	41.00 FS	*- FS
31	1	*FRONT DOOR-LH	Repair	2,909.00 FS	*- FS
32	1	*FRONT DOOR OUTER SEAL-LH	Not Necessary	166.00 FS	*- FS
33	5	*GROMMET	Necessary	13.00 FS	*10.40 FS
34	1	*FRONT PROTECRIVE FILM	Not Necessary	26.00 FS	*- FS
35	1	*FRONT DOOR ATTACHMENT PART	Not Necessary	107.00 FS	*- FS
36	1	*FRONT DOOR CATCH-LH	Not Necessary	120.00 FS	*- FS
37	1	*FRONT DOOR COVER-LH	Not Necessary	446.00 FS	*- FS
38	1	*FRONT MIRROR MOUNTING-LH	Not Necessary	1,024.00 FS	*- FS
39	1	*FRONT TURNING SIGNAL INDICATOR	Not Necessary	100.00 FS	*- FS
40	1	*FRONT ALUMINIUM RIM-LH	Not Necessary	1,262.00 FS	*- FS
41	1	*A/SEALANT	Necessary	180.00 FS	*180.00 FS
42	1	*C/WAX	Necessary	140.00 FS	*140.00 FS
43	1	*METAL FILLER POWER	Necessary	280.00 FS	*280.00 FS
44	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
45	1	*SUNDRIES	Necessary	400.00 FS	*90.56 FS
46	1	*A/B PILLAR FRAME - LH (Supplementary)	Repair	3,361.00 FS	*- FS
47	1	*FRONT WINDSCREEN (Supplementary)	Not Necessary	1,461.00 FS	*- FS
48	1	*RAIN SENSOR GEL FOIL (Supplementary)	Not Necessary	137.00 FS	*- FS
49	1	*GLASS PRIMER (Supplementary)	Not Necessary	20.00 FS	*- FS
50	1	*A-PILLAR BRACKET - LH LOWER (Supplementary)	Distorted	44.00 FS	*34.88 FS
51	1	*BATTERY CONSOLE (Supplementary)	Cracked	125.00 FS	*99.60 FS

Report was unsubmitted during this print-out.

11/16/21, 9:50 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					30,005.00	11,626.32
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS.HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	400.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,LHS FRONT DOOR AND LHS HEADLIGHT.TO CUT LHS FRONT FENDER TOP SUPPORT AND LHS A-PILLAR BRACKET.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,400.00	1,500.00
5	TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER,LHS FRONT FENDER,LHS FRONT FENDER TOP SUPPORT.BONNET,LHS FRONT DOOR,DOOR COVER,LHS UPPER A-PILLAR.LHS A-PILLAR BRACKET.LHS WING MIRROR COVER AND BOTH FRONT WHEEL ARCH TRIMS	New	8,400.00	3,700.00
6	TO RENEW LHS FRONT RIM.TO CARRY OUT PRE-POST WHEEL ALIGNMENT	New	520.00	320.00
7	TO CARRY OUT PRE-POST DIAGNOSTIC CHECK	New	384.00	384.00
8	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, A/B PILLAR TRIMS, SILL TRIMS, CARPET, ELECTRICAL COMPONENTS AND FUSE TRAYS (Supplementary)	New	1,800.00	1,800.00
9	TO RENEW FRONT WINDSCREEN TO FACILITATE RENEWAL OF A PILLAR WITH SILL PANEL (Supplementary)	New	500.00	0.00
10	TO REMOVE AND REPLACE RAIN SENSOR FOIL. TO RESET SYSTEM (Supplementary)	New	300.00	0.00
11	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN (Supplementary)	New	200.00	0.00
12	TO CUT OUT AND WELD LHS A-PILLAR (Supplementary)	New	2,400.00	1,000.00
13	TO RESPRAY LHS A-PILLAR (Supplementary)	New	1,000.00	550.00
14	TO REMOVE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY TO FACILITATE RENEWAL OF LHS A PILLAR WITH SILL PANEL (Supplementary)	New	3,200.00	3,200.00
Gross Labour Cost (\$\$)			26,264.00	13,344.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >