

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21007129/AQCE2

Date: 29/09/2021

REFERENCE

Insured/Claimant: RAFEEL AHMED S/O ABDUL MAJEED
Date of Loss: 25/06/2021

Policy No: 1800067648-01
Nature of Claim: OD

Claim No: 5621959049SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGR1166X**
Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK062064
Reg. Date: 19/06/2018 (Man. Year: 2018) Chassis No: WAUZZZF51JA101867
Colour: White Odometer: 102201 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$138,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,068.00	12,953.12	10,114.88	43.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,902.00	5,572.00	9,330.00	62.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	37,970.00	18,525.12	19,444.88	51.21
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	37,170.00	17,725.12	19,444.88	52.31
+ GST 7.00/7.00% (\$\$)	2,601.90	1,240.76	1,361.14	52.31
Nett Amount (\$\$)	39,771.90	18,965.88	20,806.02	52.31

INSPECTION

Date of Assignment: 29/06/2021

Date Inspected: 28/06/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	228.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Deformed	63.00 FS	*50.08 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	474.00 FS	*378.80 FS
8	1		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER FORM	Not Necessary	124.00 FS	*- FS
10	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	36.00 FS	*28.72 FS
12	1		*FRONT BUMPER BRACKET - RH	Not Necessary	214.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
14	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
15	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
17	2		*FRONT BUMPER PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
18	4		*FRONT BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
19	1		*SET FRONT BUMPER WIRING	Not Necessary	510.00 FS	*- FS
20	1		*HORN - LOW TONE	Not Necessary	126.00 FS	*- FS
21	1		*HORN BRACKET	Not Necessary	29.00 FS	*- FS
22	1		*FRONT FENDER - RH	Dented	1,060.00 FS	*848.00 FS
23	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
24	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	74.00 FS	*- FS
25	1		*FRONT FENDER BRACKET - RH	Distorted	35.00 FS	*27.92 FS
26	5		*FRONT FENDER RIVET	Necessary	17.00 FS	*13.20 FS
27	1		*FRONT FENDER DEFORMATION BRACKET - RH	Damaged	49.00 FS	*39.20 FS
28	1		*FRONT FENDER BRACKET - RH FRONT	Damaged	35.00 FS	*27.92 FS
29	1		*FRONT FENDER BRACE - RH	Bent	118.00 FS	*94.40 FS
30	1		*FRONT FENDER CHROME TRIM - RH	Necessary	164.00 FS	*130.80 FS
31	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	275.00 FS	*219.60 FS
32	1		*FRONT WHEEL HOUSING LINER ATTACHMENT	Not Necessary	169.00 FS	*- FS
33	1		*FRONT WHEEL SPOILER - RH	Cracked	73.00 FS	*58.40 FS
34	1		*FRONT WHEEL SPOILER TRIM - RH	Not Necessary	51.00 FS	*- FS
35	1		*FRONT WHEEL SPOILER TRIM BRACKET - RH	Not Necessary	24.00 FS	*- FS
36	2		*FRONT FENDER TOP COVER	Not Necessary	16.00 FS	*- FS
37	1		*FRONT BONNET	Dented	3,312.00 FS	*2,649.60 FS
38	3		*FRONT BONNET RETAINING CLIP	Not Necessary	4.00 FS	*- FS
39	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	126.00 FS	*- FS
40	2		*FRONT BONNET HINGE	Not Necessary	838.00 FS	*- FS
41	1		*FRONT BONNET IMPACT PROTECTION (3PCS)	Necessary	84.00 FS	*65.68 FS
42	1		*FRONT BONNET SOUND ABSORBER	Not Necessary	343.00 FS	*- FS
43	1		*FRONT BONNET STRIKER	Not Necessary	50.00 FS	*- FS
44	1		*FRONT BONNET LOCK	Not Necessary	214.00 FS	*- FS
45	1		*FRONT HEADLIGHT - RH	Cracked	7,902.00 FS	*6,321.60 FS
46	1		*FRONT HEADLIGHT LIFT CYLINDER - RH	Damaged	198.00 FS	*158.40 FS
47	1		*FRONT HEADLIGHT LIFT CYLINDER BRACKET - RH	Not Necessary	15.00 FS	*- FS
48	1		*FRONT HEADLIGHT LIFT CYLINDER HOSE - RH	Not Necessary	86.00 FS	*- FS
49	1		*FRONT LOCK CARRIER	Not Necessary	1,016.00 FS	*- FS
50	1		*FRONT SENSOR BRACKET	Not Necessary	19.00 FS	*- FS
51	6		*COOLANT	Not Necessary	142.00 FS	*- FS
52	3		*FRONT RADIATOR AIR GUIDE	Not Necessary	63.00 FS	*- FS
53	1		*FRONT RADIATOR GRILLE	Not Necessary	0.00 FS	*- FS
54	1		*FRONT NO. PLATE	Not Necessary	80.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*SUNDRIES	Necessary	400.00 FS	*40.00 FS
56	1		*FRONT FENDER TOP LEDGE COVER RH	Not Necessary	36.00 FS	*- FS
			(Supplementary)			
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	23,068.00 12,953.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,700.00	0.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,500.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES AND RHS FRONT DOOR	New	4,400.00	1,650.00
7	TO REAPPLY STICKER ON AFFECTED PANELS	New	350.00	350.00
8	TO REAPPLY PAINT PROTECTION ON FRONT BONNET, HEADLIGHT AND FRONT BUMPER (BY OWNER)	New	1,500.00	1,150.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			14,902.00	5,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >