

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 4254J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR O/S	DENTED / WARPED	1,582.00	1,582.00
1	FRONT DOOR OUTER PROTECTOR O/S	SERVICEABLE	204.00	-
1	SET FRONT DOOR FRAME BLACK GARNISH O/S	NECESSARY	98.00	98.00
1	FRONT DOOR INNER RUBBER O/S	NOT NECESSARY	145.00	-
1	REAR DOOR O/S	DENTED / BENT	1,483.00	1,483.00
1	REAR DOOR OUTER PROTECTOR O/S	SERVICEABLE	242.00	-
1	SET REAR DOOR FRAME BLACK GARNISH O/S	NECESSARY	98.00	98.00
1	REAR DOOR INNER RUBBER O/S	NOT NECESSARY	122.00	-
1	REAR DOOR LOWER STICKER O/S	NECESSARY	45.00	45.00
1	REAR SPORT RIM O/S	TO REPAIR SEE LABOUR	850.00	-
1	REAR WHEEL HUB BEARING O/S	NOT NECESSARY	426.00	-
	LESS 10% DISCOUNT		-	-330.60
			5,295.00	2,975.40
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO TRANSFER BOTH DOOR MECHANISM.		150.00	120.00
	TO SPRAY RUST PROOFING.		80.00	60.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.	NOT NECESSARY	120.00	-
	TO CONDUCT WHEEL ALIGNMENT.		100.00	60.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR SPORT RIM O/S.		500.00	300.00
	TO PUTTY & SPRAY PAINTING.		900.00	600.00
			1,900.00	1,160.00
	GRAND TOTAL		7,195.00	4,135.40
	RECOMMENDED COST OF LUMP SUM REPAIRS			3,300.00

RECOMMENDED COST OF LUMP SUM REPAIRS		3,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/TP21007132/Utf3e2

CHUA KANG SENG

Licensed Appraiser