

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007135/UPS3Q2
Date: 17/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900080072
Claimant Vehicle No :	SKH4416K	Insured Vehicle No :	SMJ989R
Date of Loss:	26/06/2021	Nature of Claim:	TP
		Claim No:	3350299529SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH4416K	Engine No:	CAXC37869
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI (A)	Chassis No:	WVWZZZ16ZDM028864
Reg. Date:	07/12/2012 (Man. Year: 2012)	Odometer:	101443 km
Colour:	Beige		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,577.01	6,887.49	6,689.52	49.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	2,060.00	1,760.00	46.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,397.01	8,947.49	8,449.52	48.57
Approved Total (Overridden) (S\$)		6,500.00		

(S\$)	17,397.01	6,500.00	10,897.01	62.64
+ GST 7.00/7.00% (S\$)	1,217.79	455.00	762.79	62.64
Nett Amount (S\$)	18,614.80	6,955.00	11,659.80	62.64
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
Nett Liability (S\$)		7,555.00		

INSPECTION

Date of Assignment: 29/06/2021

Date Inspected: 29/06/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Automobile Integrated Management Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
 Singapore 415933

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent / Buckled	1,895.50 FL	*1,650.21 FL
2	1		*REAR BOOT LOGO	Not Necessary	128.85 FL	*- FL
3	1		*REAR BOOT EMBLEM JETTA	Necessary	81.50 FL	*81.50 FL
4	1		*REAR BOOT EMBLEM TSI	Necessary	68.85 FL	*68.85 FL
5	1		*REAR BOOT LAMPS-L/R	O/S Broken	598.70 FL	*299.35 FL
6	1		*REAR BOOT INNER LOCK	Serviceable	280.63 FL	*- FL
7	1		*REAR BOOT INNER TRIM	Not Necessary	291.77 FL	*- FL
8	1		*REAR BOOT W/STRIP	Twisted	211.43 FL	*211.43 FL
9	2		*REAR BOOT HINGES -L/R	Not Necessary	341.50 FL	*- FL
10	2		*REAR BOOT DAMPERS -L/R	Not Necessary	230.60 FL	*- FL
11	1		*REAR BUMPER	Distorted	1,480.75 FL	*1,123.32 FL
12	1		*REAR BUMPER REFLECTOR -RH	Cracked	89.95 FL	*89.95 FL
13	1		*REAR BUMPER DIFUSSER	Distorted	681.90 FL	*681.90 FL
14	1		*REAR BUMPER CTR GUIDE	Twisted	180.95 FL	*180.95 FL
15	1		*REAR BUMPER SIDE GUIDES -L/R	O/S Cracked	220.50 FL	*110.25 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	775.90 FL	*645.35 FL
17	1		*REAR END PANEL	Badly Dented	1,150.60 FL	*825.32 FL
18	1		*REAR END PANEL TRIM	Twisted	296.72 FL	*296.72 FL
19	1		*REAR FLOOR BOARD	Not Necessary	467.32 FL	*- FL
20	1		*REAR FLOOR TRAY	Not Necessary	297.35 FL	*- FL
21	1		*REAR FLOOR PANEL	Repair	825.60 FL	*- FL
22	1		*REAR FENDER -RH	Repair	1,950.60 FL	*- FL
23	1		*REAR FENDER INNER TRIM -RH	Not Necessary	411.35 FL	*- FL
24	1		*REAR FENDER INNER SHIELD	Torn	191.35 FL	*191.35 FL
25	1		*REAR FENDER LOWER COVER	Torn	141.25 FL	*141.25 FL
26	1		*REAR TAILLAMP PANEL	Dented	271.55 FL	*271.55 FL
27	1		*REAR TAILLAMPS -L/R	O/S Broken	1,022.60 FL	*511.30 FL
28	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
29	1		*SET REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
31	1		*SET REAR BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,035.57	7,625.55
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,458.56	738.06

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					13,577.01	6,887.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	80.00
3	TO REMOVE, REFIX REAR WINDSCREEN	New	180.00	0.00
4	TO REMOVE,REFIX REVERSE SENSOR /CAMERA	New	120.00	50.00
5	TO RESPRAY UNDERCOATING	New	150.00	60.00
6	TO RESPRAY PAINTING & ETC	New	1,400.00	1,000.00
7	PANEL BEATING ,CUT,WELD ,REMOVE & REPLACING ABOVE PARTS	New	1,800.00	850.00
Gross Labour Cost (S\$)			3,820.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >