

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007137/KPA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800069498
Claimant Vehicle No :	GBK5275J	Insured Vehicle No :	SMA1967U
Date of Loss:	26/06/2021	Nature of Claim:	TP
		Claim No:	8477776449SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK5275J		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KDB046010
Reg. Date:	31/08/2020 (Man. Year: 2020)	Chassis No:	JTFHT02PX09990310
Colour:	Silver	Odometer:	21472 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,664.89	7,397.77	1,267.12	14.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	3,380.00	680.00	16.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,724.89	10,777.77	1,947.12	15.30
+ GST 7.00/7.00% (\$\$)	890.74	754.44	136.30	15.30
Nett Amount (\$\$)	13,615.63	11,532.21	2,083.42	15.30
+ Car Rental (12.0 x S\$100.00/day) (\$\$)		1,200.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		12,734.21		
Global Sum Settlement (\$\$)		12,700.00		

INSPECTION

Date of Assignment:	29/06/2021	
Date Inspected:	29/06/2021 Inspected At:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT Singapore 568047
Estimated Period of Repair:	11.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	454.30 FL	*454.30 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Cracked	23.40 FL	*23.40 FL
3	6		*REAR BUMPER CLIP	Necessary	17.70 FL	*17.70 FL
4	1		*REAR BUMPER MUDFLAP	Distorted	127.85 FL	*127.85 FL
5	1		*REAR TAILGATE	Bent	2,162.70 FL	*2,162.70 FL
6	1		*TAILGATE INNER RUBBER	Serviceable	408.40 FL	*- FL
7	1		*TAILGATE LOGO	Necessary	67.80 FL	*67.80 FL
8	1		*TAILGATE EMBLEM HIACE	Necessary	48.60 FL	*48.60 FL
9	1		*RH TAILLAMP	Broken	367.60 FL	*367.60 FL
10	1		*RH TAILLAMP PANEL	Bent	570.30 FL	*570.30 FL
11	1		*RH TAILLAMP CLIP	Necessary	3.50 FL	*3.50 FL
12	1		*RH TAILLAMP LOWER GARNISH	Cracked	93.90 FL	*93.90 FL
13	1		*REAR END PANEL OUTER	Bent	342.50 FL	*342.50 FL
14	1		*REAR END PANEL INNER	Bent	1,104.70 FL	*1,104.70 FL
15	1		*REAR RH SIDE PANEL	Bent	1,546.90 FL	*1,546.90 FL
16	1		*REAR RH SIDE INNER PANEL	Repair	1,281.10 FL	*- FL
17	1		*REAR RH SIDE PANEL INNER AIR SCOPE GRILLE	Cracked	43.80 FL	*43.80 FL
18	1		*REAR RH SIDE PANEL INNER TRIM BOARD	Distorted	137.40 FL	*137.40 FL
19	1		*RH SLIDING DOOR	Bent	1,916.11 FL	*1,916.11 FL
20	1		*REAR RH WHEEL HOUSE COVER	Dented	212.20 FL	*212.20 FL
21	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
22	1		*TAILGATE STICKER 70KM/HR	Necessary	10.00 FS	*10.00 FS
23	1		*SET REVERSE SENSOR	Torn	200.00 FS	*200.00 FS
24	1		*RH TAILLAMP INNER PANEL	Bent	289.10 FL	*289.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX CARPET ,TOP ROOF LINING ,WOODEN FLOORBOARD GARNISH TO FACILITATE REPAIR	New	250.00	180.00
3	REMOVE & REFIX REAR EXHAUST & REALIGN THE SAME	New	80.00	60.00
4	R&R REAR BUMPER & ATTACHMENTS ,TAILLAMPS ,TAILGATE & ATTACHMENTS ,RH SLIDING DOOR & ATTACHMENTS CUT ,WELD & RENEW REAR END PANEL OTHER & INNER ,REAR RH SIDE PANEL & INNER PANEL K&R REAR FLOORBOARD PANEL ,RH CHASSIS FRAME ,RH WHEEL HOUSING & REALIGN THE SAME	New	2,000.00	1,600.00
5	PUTTY & RESPRAY RR BUMPER & PARKING SENSORS ,TAILGATE ,RR END PANEL OUTER & INNER ,RH SIDE PANEL & INNER PANEL ,TAILLAMP PANEL & LOWER GARNISH ,REAR FLOORBOARD PANEL ,RH CHASSIS FRAME ,RH WHEEL HOUSING ,RH SLIDING DOOR ,FRT RH DOOR PILLAR REAR & ALL AFFECTED AREAS	New	1,400.00	1,300.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	0.00
7	RUSTPROOFING	New	150.00	120.00
Gross Labour Cost (S\$)			4,060.00	3,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >