



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 4411A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	696.00	605.00
4	REAR BUMPER PARKING SENSOR @\$187.60	DAMAGED	750.40	750.40
1	REAR BUMPER TOWING COVER	SCRATCHED	22.00	8.00
1	REAR BUMPER LH REFLECTOR	CUT	129.00	129.00
1	REAR BUMPER CENTRE PAD	DEFORMED	103.00	103.00
1	REAR BUMPER LOWER SPOILER	DEFORMED	566.00	566.00
1	REAR BUMPER RH SIDE RETAINER	DEFORMED	52.00	35.00
1	REAR BUMPER LH SIDE RETAINER	NOT NECESSARY	52.00	-
1	REAR BUMPER REINFORCEMENT	BENT	360.00	360.00
1	REAR BUMPER ANTENNA SENSOR	BROKEN	351.00	53.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	20.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	526.00	-
1	REAR EXHAUST	DENTED	711.40	711.40
	LESS 10% DISCOUNT		-436.88	-334.08
			3,931.92	3,006.72
	<u>LABOUR</u>			
	TO REPAIR REAR DAMAGES.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		580.00	500.00
	TO SPRAY PAINTING.		780.00	600.00
			1,360.00	1,100.00
	GRAND TOTAL		5,291.92	4,106.72
	RECOMMENDED COST OF REPAIRS			4,106.72

Report Ref No. CS/SMR21007140/Guf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.