


ASS. REC BY: 62.

ASSIGNMENT

CS/SMR21007140/Guf3

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKV 4411A
 at Workshop m/s Vin's Auto
 of _____
 Insured: SHF 356Y
 Policy No. _____
 Claims No. TAX/06/21/2058
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$78K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKV4411A Yr Regn: 18 SEP 2015
 Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: KIA Sorento 2.4 c.c 2359
 Colour: Red A/C: Insured / Std / NI / NA
 Sp Reading: 9/200 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNA PH 813 M 6 512 8127
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/60R18
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 30-06-21
 Survey held at w/s 11:30
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirmed final fig P/P \$4106.72, 5 repair days.
 (RED \$1185.20; 22%)

Date/Time, File Pass to?

1) 27/7 TYPIST

Date/Time, File Return to?

2)

Report Estimated TP \$4106.72

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Other:



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/062021/4882

Accident date : 28/6/2021

Your Ref : SHF356Y

Invoice No.:

Date : 29/6/2021

MOTOR CLAIM DEPARTMENT
FIRST CAPITAL INSURANCE LTD

36 Robinson Road

#16-01 City House

Singapore 068877

ESTIMATE COST OF REPAIRS TO

Model : Kia Sorento 2.4 (A) GDI

Vehicle No. : SKV4411A

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

1	pc	Rear bumper / <i>re</i>	\$	696.00
4	pcs	Rear bumper parking sensor @ \$187.60 / <i>DM</i>	\$	750.40
1	pc	Rear bumper towing cover / <i>scr</i>	\$	22.00
1	pc	Rear bumper LH reflector / <i>cut</i>	\$	129.00
1	pc	Rear bumper centre pad / <i>re</i>	\$	103.00
1	pc	Rear bumper lower spoiler / <i>re</i>	\$	566.00
1	pc	Rear bumper RH side retainer / <i>re</i>	\$	52.00
1	pc	Rear bumper LH side retainer / <i>re</i>	\$	52.00
1	pc	Rear bumper reinforcement / <i>BT</i>	\$	360.00
1	pc	Rear bumper antenna sensor / <i>BR</i>	\$	351.00
10	pcs	Rear bumper clips @ \$5.00 / <i>mc</i>	\$	50.00
1	pc	Rear end panel / <i>re</i>	\$	526.00
1	pc	Rear exhaust / <i>re</i>	\$	711.40
			\$	4,368.80
		Less 10%	\$	(436.88)
			\$	3,931.92
		To repair rear damages	\$	580.00
		To spray painting	\$	780.00
			\$	5,291.92

VIN'S MOTOR PTE LTD

5 Days. (S)

part by part.

before paint photos.

One Qian - 82880282

30/6/2021.

400.00

400.60