

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007144/KRA3Q2
Date: 11/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800130732
Claimant Vehicle No :	SMK5688X	Insured Vehicle No :	SKU5745K
Date of Loss:	25/06/2021	Nature of Claim:	TP
		Claim No:	6649636075SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK5688X		
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Engine No:	G4FGKU117521
Reg. Date:	16/04/2019 (Man. Year: 2019)	Chassis No:	KMHD841CMKU885467
Colour:	Metallic Silver	Odometer:	53611 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,386.40	850.16	536.24	38.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	650.00	1,050.00	61.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,086.40	1,500.16	1,586.24	51.39
+ GST 7.00/7.00% (S\$)	216.05	105.01	111.04	51.40

Nett Amount (S\$)	3,302.45	1,605.17	1,697.28	51.39
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		1,905.17		

INSPECTION

Date of Assignment: 29/06/2021

Date Inspected: 30/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

City Auto Pte Ltd (Sin Ming) (HQ)
 Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est
 Singapore 575643

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER)	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER (LOWER)	Mtg Cracked	353.30 FL	*353.30 FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	294.80 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT BRACKET	Serviceable	48.90 FL	*- FL
5	2		*REAR BUMPER RETAINER	Serviceable	88.00 FL	*- FL
6	2		*REAR BUMPER LOWER BRACKET	Serviceable	23.60 FL	*- FL
7	2		*REAR BUMPER UPPER BRACKET	Serviceable	23.60 FL	*- FL
8	1		*REVERSE SENSOR	Serviceable	132.00 FL	*- FL
9	1		*REAR BOOT EMBLEM -AVANTE	Not Necessary	31.20 FL	*- FL
10	1		*REAR BOOT EMBLEM -S	Not Necessary	28.20 FL	*- FL
11	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,683.00	1,012.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	296.60	162.54
Total Parts (\$\$)	1,386.40	850.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REVERSE SENSOR	New	40.00	40.00
2	TO CHECK WIRING AND LIGHTING	New	60.00	10.00
3	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	800.00	200.00
4	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	800.00	400.00
Gross Labour Cost (\$\$)			1,700.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >