

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21007145/EQF3E2

Date: 09/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070095895		
Claimant Vehicle No :	SME7746E	Insured Vehicle No :	GBH6271D		
Date of Loss:	26/06/2021	Nature of Claim:	TP	Claim No:	9016542657SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME7746E	Engine No:	1ZR0C39998
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Standard (A)	Chassis No:	MR053REH604591679
Reg. Date:	16/10/2018 (Man. Year: 2018)	Odometer:	56241 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	29/06/2021	
Date Inspected:	30/06/2021	Inspected At: Tian Siang Motor (HQ) 27A Jurong Port Road Blk #01-18, Jurong Ind Est Singapore 619101
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$77,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Crushed	0.00 F	*- F
3	1		*FRT BUMPER	Broken	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1		*FRT BUMPER SPONGE	Broken	0.00 F	*- F
7	1		*FRT BUMPER GRILLE LOWER	Broken	0.00 F	*- F
8	1		*FRT GRILLE	Broken	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
10	1		*FRT GRILLE CHROME MOULDING	Broken	0.00 F	*- F
11	1		*FRT LH HEADLAMP ASSY	Crushed	0.00 F	*- F
12	1		*FRT RH HEADLAMP ASSY	Crushed	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >