

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21007151/KGA3Q2**Date:** 27/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800027037
Claimant Vehicle No :	SHC5682M	Insured Vehicle No :	SLX2898U
Date of Loss:	24/06/2021	Nature of Claim:	TP
		Claim No:	5055019474SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5682M		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H82474
Reg. Date:	29/01/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FU103093690
Colour:	Metallic Pearl White/Red	Odometer:	25860 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 8 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,507.67	17,103.67	13,404.00	43.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	2,890.00	2,210.00	43.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,607.67	19,993.67	15,614.00	43.85
+ GST 7.00/7.00% (S\$)	2,492.54	1,399.56	1,092.98	43.85
Nett Amount (S\$)	38,100.21	21,393.23	16,706.98	43.85
+ Loss of Use (13.0 x S\$50.00/day) (S\$)		650.00		
+ Car Rental (13.0 x S\$96.30/day) (S\$)		1,251.90		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		23,302.58		
Global Sum Settlement (S\$)		23,300.00		

INSPECTION

Date of Assignment:	28/06/2021	
Date Inspected:	28/06/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Mtg Cracked	521.00 FL	*521.00 FL
2	1		*UNIT ASSY ,HEADLAMP ,LH	Serviceable	2,637.60 FL	*- FL
3	1		*COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1	Serviceable	3,772.50 FL	*- FL
4	1		*FENDER SUB-ASSY ,FRONT LH	Bent	977.80 FL	*977.80 FL
5	1		*LINER ,FRONT FENDER ,LH	Distorted	210.30 FL	*210.30 FL
6	1		*EMBLEM ,SIDE PANEL	Necessary	54.60 FL	*54.60 FL
7	1		*PANEL SUB-ASSY,FRONT DOOR ,LH	Bent	1,300.70 FL	*1,300.70 FL
8	1		*WEATHERSTRIP ,FRONT DOOR ,LH	Serviceable	231.30 FL	*- FL
9	1		*HINGE ASSY ,FRONT DOOR ,LOWER LH	Bent	110.60 FL	*110.60 FL
10	1		*HINGE ASSY ,FRONT DOOR ,UPPER LH	Bent	97.50 FL	*97.50 FL
11	1		*TAPE ,BLACK OUT ,NO.1 FRT LH	Necessary	13.30 FL	*13.30 FL
12	1		*TAPE ,BLACK OUT ,NO.2 FRT LH	Necessary	43.50 FL	*43.50 FL
13	1		*TAPE ,BLACK OUT ,NO.3 FRT LH	Necessary	26.30 FL	*26.30 FL
14	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT LH	Jammed	926.00 FL	*926.00 FL
15	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,LH	Bent	238.30 FL	*238.30 FL
16	1		*FRAME SUB-ASSY ,FRONT DOOR OUTSIDE HANDLE ,LH	Serviceable	193.50 FL	*- FL
17	1		*HANDLE ASSY ,FRONT DOOR OUTSIDE ,LH	Serviceable	390.60 FL	*- FL
18	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Bent	1,294.90 FL	*1,294.90 FL
19	1		*WEATHERSTRIP ,REAR DOOR OPENING TRIM ,LH	Serviceable	293.00 FL	*- FL
20	1		*HINGE ASSY ,REAR DOOR ,LOWER LH	Repair	87.10 FL	*- FL
21	1		*HINGE ASSY ,REAR DOOR ,UPPER LH	Repair	98.90 FL	*- FL
22	1		*TAPE, BLACK OUT NO.1 REAR LH	Necessary	21.90 FL	*21.90 FL
23	1		*TAPE, BLACK OUT NO.2 REAR LH	Necessary	34.90 FL	*34.90 FL
24	1		*TAPE, BLACK OUT NO.3 REAR LH	Necessary	15.40 FL	*15.40 FL
25	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,LH	Repair	926.00 FL	*- FL
26	1		*REGULATOR SUB-ASSY ,REAR DOOR WINDOW ,LH	Serviceable	206.70 FL	*- FL
27	1		*PANEL SUB-ASSY ,QUARTER ,LH	Bent	871.50 FL	*871.50 FL
28	1		*LINER ,REAR WHEEL HOUSE ,LH	Serviceable	139.80 FL	*- FL
29	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Distorted	594.80 FL	*594.80 FL
30	1		*PANEL SUB-ASSY ,QUARTER ,LH	Repeated	871.50 FL	*- FL
31	1		*LINER ,REAR WHEEL HOUSE ,LH	Serviceable	139.80 FL	*- FL
32	1		*SHAFT ASSY ,FRONT DRIVE ,LH	Bent	1,251.70 FL	*1,251.70 FL
33	1		*KNUCKLE STEERING ,LH	Bent	663.40 FL	*663.40 FL
34	1		*ARM SUB-ASSY ,FRONT SUSPENSION ,LOWER NO.1 LH	Distorted	760.10 FL	*760.10 FL
35	1		*ABSORBER ASSY ,CHECK FRONT LH	Bent	472.30 FL	*472.30 FL
36	1		*HEADLINING ASSY ,ROOF	Torn	2,125.70 FL	*2,125.70 FL
37	1		*AIR BAR ASSY ,CURTAIN SHIELD ,LH	Burst	1,748.10 FL	*1,748.10 FL
38	1		*SENSOR ASSY ,SIDE AIR BAR ,LH NO.2	Necessary	709.30 FL	*709.30 FL
39	1		*SENSOR ,DOOR SIDE AIR BAG ,LH	Necessary	379.20 FL	*379.20 FL
40	1		*COMPUTER ASSY ,AIR BAG	Necessary	1,546.00 FL	*1,546.00 FL
41	1		*AIR BAG ASSY ,FRONT SEAT ,LH	Burst	1,008.80 FL	*1,008.80 FL
42	1		*BELT ASSY ,REAR SEAT ,OUTER CENTER	Serviceable	628.10 FL	*- FL
43	1		*BELT ASSY ,REAR SEAT 3 POINT TYPE ,OUTER LH	Jammed	995.10 FL	*995.10 FL
44	1		*BELT ASSY ,REAR SEAT ,INNER W/CENTER ,LH	Serviceable	251.60 FL	*- FL
45	1		*BELT ASSY ,REAR SEAT ,INNER W/CENTER ,RH	Serviceable	251.60 FL	*- FL
46	1		*BELT ASSY ,REAR SEAT 3 POINT TYPE ,OUTER ,RH	Jammed	995.10 FL	*995.10 FL
47	1		*BELT ASSY ,FRONT SEAT INNER ,RH	Serviceable	177.00 FL	*- FL
48	1		*BELT ASSY ,FRONT SEAT INNER ,LH	Serviceable	177.00 FL	*- FL
49	1		*BELT ASSY ,FRONT SEAT OUTER ,RH	Jammed	995.10 FL	*995.10 FL
50	1		*BELT ASSY ,FRONT SEAT OUTER ,LH	Jammed	995.10 FL	*995.10 FL
51	1		*FRAME SUB-ASSY ,FRONT DOOR ,FRONT LOWER LH	Distorted	144.60 FL	*144.60 FL
52	1		*FRONT BUMPER SIDE CLIP	Necessary	60.00 FS	*50.00 FS
53	1		*SET FRONT BUMPER CLIP	Not Necessary	85.00 FS	*- FS
54	1		*TYRE	Serviceable	350.00 FS	*- FS
55	1		*HUB CAP	Cracked	211.50 FS	*211.50 FS

Report was unsubmitted during this print-out.

1/27/22, 9:58 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*RIM	Serviceable	1,879.40 FS	*- FS
57	2		*FENDER CLIP	Necessary	150.00 FS	*50.00 FS
58	2		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
59	1		*SET DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
60	1		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	130.00 FS	*- FS
61	1		*DOOR STICKER TRANS-CAB	Necessary	350.00 FS	*60.00 FS
62	1		*DOOR STICKER TEL NO	Necessary	1,879.40 FS	*60.00 FS
63	1		*SET CLIP ,ROCKER PANEL MOULDING	Necessary	65.00 FS	*65.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					38,911.80	22,639.40
- List Item Discount on L Items 25.00/25.00% (S\$)					8,404.13	5,535.73
Total Parts (S\$)					30,507.67	17,103.67
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	120.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	120.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	1,000.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	1,540.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	20.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	30.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENT AND	New	170.00	0.00
Gross Labour Cost (\$\$)			5,100.00	2,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >