

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007157/GTCN2**Date:** 04/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00093082100

Claimant Vehicle No : SMD2363P **Insured Vehicle No :** SJR8985S

Date of Loss: 26/06/2021 Nature of Claim: TP Claim No: SNM21D203609/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD2363P**

Make & Model: BLUECAR BLUECAR, (A) Engine No: HIDDEN

Reg. Date: 08/08/2018 (Man. Year: 2017) Chassis No: VL4BCEB4RJT003274

Colour: White Odometer: 64850 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65R15 Rear Tyre Size: 175/65R15

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,715.80	3,609.20	1,106.60	23.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	850.00	1,050.00	55.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,615.80	4,459.20	2,156.60	32.60
+ GST 7.00/7.00% (\$\$)	463.11	312.14	150.97	32.60
Nett Amount (\$\$)	7,078.91	4,771.34	2,307.57	32.60

INSPECTION

Date of Assignment: 29/06/2021

Date Inspected: 29/06/2021 Inspected At: Indeco Engineers Pte Ltd (Defu)
No. 39 Defu Lane 12
Singapore 539315

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2022)
Parts:	144	BLUECAR BLUECAR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD2363P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID GLASS (WCP)	Broken	966.00 F	*966.00 F
2	1		*HATCH PININFARINA LOGO (WCP)	Necessary	32.00 F	*32.00 F
3	1		*HATCH PININFARINA EMBLEM (WCP)	Missing	62.00 F	*62.00 F
4	4		*BOOT LID GLASS SCREW COVER (WCP)	Not Necessary	72.00 F	*- F
5	4		*BOOT LID GLASS SCREW (WCP)	Not Necessary	8.00 F	*- F
6	1		*BOOT LID GLASS HINGE ASSY (WCP)	Not Necessary	154.00 F	*- F
7	1		*BOOT LID GLASS DAMPER RH (WCP)	Not Necessary	36.00 F	*- F
8	1		*BOOT LID GLASS DAMPER LH (WCP)	Not Necessary	36.00 F	*- F
9	1		*BOOT LID GLASS LOCK (WCP)	Not Necessary	132.00 F	*- F
10	1		*BOOT LID GLASS LOCK CATCH (WCP)	Not Necessary	55.00 F	*- F
11	1		*BOOT LID GLASS CATCH COVER (WCP)	Not Necessary	35.00 F	*- F
12	1		*REAR WEATHER STRIP (WCP)	Cut	84.00 F	*84.00 F
13	1		*REAR TRIM (WCP)	Scratched	128.00 F	*128.00 F
14	1		*REAR BUMPER (WCP)	Deformed	1,405.00 F	*1,405.00 F
15	1		*REAR BUMPER REINFORCEMENT (WCP)	Not Necessary	82.00 F	*- F
16	2		*REAR BUMPER REINFORCEMENT BRACKET (WCP)	Not Necessary	86.00 F	*- F
17	1		*REAR BUMPER NUMBER PLATE LIGHT (WCP)	Broken (1 Pc only)	210.00 F	*105.00 F
			(2 Pcs)			
18	1		*REAR BOOT LID STICKER	Missing	40.00 FS	*40.00 FS
19	1		*REAR BUMPER MARKETING DECAL	Necessary	180.00 FS	*180.00 FS
20	1		*REAR NUMBER PLATE	Missing	45.00 FS	*45.00 FS
21	1		*REAR BUMPER REFLECTOR LAMP LH (WCP)	Cracked	126.00 F	*126.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,974.00	3,173.00
+ Margin on L,N Items 20.00/15.00% (\$\$)	741.80	436.20
Total Parts (\$\$)	4,715.80	3,609.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	1,000.00	500.00
2	TO PUTTY,RESPRAY REAR END PANEL AND REAR BUMPER	New	600.00	200.00
3	TO REPLACE REAR WINDSCREEN GLASS & CLEAN UP SHATTERED GLASS	New	150.00	120.00
4	TO CHECK WIRING AND RESET	New	150.00	30.00
Gross Labour Cost (\$)			1,900.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >