

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 9294G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REVERSE SENSOR	TORN	200.00	200.00
1	END PANEL GARNISH	NOT NECESSARY	230.00	-
1	TAIL LAMP LOWER BRACKET	NOT NECESSARY	120.00	-
1	REAR LEFT TAILGATE BRACKET	NOT NECESSARY	120.00	-
1	REAR LEFT WHEEL BEARING	NOT NECESSARY	150.00	-
1	SPARE TYRE BOARD	NOT NECESSARY	80.00	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	350.00	-
1	BUMPER BRACKET	BROKEN	150.00	90.00
1	REAR LEFT ABSORBER	NOT NECESSARY	230.00	-
1	REAR LEFT MUDGUARD	NOT NECESSARY	80.00	-
1	LEFT BOOTLID LAMP	NOT NECESSARY	200.00	-
1	LEFT TAIL LIGHT	NOT NECESSARY	200.00	-
1	REAR UNDERCARRIAGE (LOWER SPOILER)	BROKEN	900.00	300.00
1	BOOT CHROME GARNISH	NOT NECESSARY	250.00	-
1	REAR BUMPER	DENTED	650.00	546.00
1	END PANEL	NOT NECESSARY	800.00	-
	LESS 15% DISCOUNT		-	-170.40
			4,710.00	965.60
	<u>LABOUR</u>			
	CHECKING OF WIRING,LIGHTINGAND RESETTING.		300.00	30.00
	REMOVE AND REFIT REAR UNDERCARRIAGE.	NOT NECESSARY	500.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	REMOVE AND REPLACE DAMAGED PARTS.	NOT NECESSARY	800.00	-
	APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		800.00	30.00
	WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS,REPAIRS INCLUDING CUT AND WELD,REALIGN BODY STRUCTURE.		1,500.00	300.00

Report Ref No. CS/AGI21007159/Etf3n2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,400.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	RESPRAY INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00
			5,000.00	760.00
	GRAND TOTAL		9,710.00	1,725.60

Report Ref No. CS/AGI21007159/Etf3n2

**RECOMMENDED COST OF LUMP SUM REPAIRS** 

(TO ITS PRE-ACCIDENT CONDITION)



**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.