

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21007163/RPA3Q2**Date:** 10/10/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMB184M**Insured Vehicle No :** GBK1112Y

Date of Loss: 05/06/2021

Nature of Claim:

TP

Claim No: 8866519785SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMB184M**

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A)

Engine No: 90292600910043

Reg. Date: 18/11/2011 (Man. Year: 2011)

Chassis No: WEB62808323122712

Colour: Multi-colour

Odometer: 0 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Firenza 8 mm

Rear Left Side: Firenza 8/8 mm

Front Right Side: Firenza 8 mm

Rear Right Side: Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,283.67	13,653.25	1,630.42	10.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,806.00	3,014.00	792.00	20.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,089.67	16,667.25	2,422.42	12.69
Approved Total (Overridden) (S\$)		13,950.00		
Nett Amount (S\$)	19,089.67	13,950.00	5,139.67	26.92
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 28/06/2021

Date Inspected: 28/06/2021 Inspected At:

Strides Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FLAP:REAR END FOR MB CITARO BUS	Bent	5,573.10 F	*5,573.10 FL
2	1		*LAMP,TAIL:REAR LH ,FOR MB CITARO O530	Broken	1,261.71 F	*1,261.71 FL
3	1		*BRACKET :LH,FOR MB CITARO O530	*Check	219.09 F	*- FL
4	1		*LAMP ,SIDE MARKER:FOR MB CITARO O530 BUS	Scratched	94.50 F	*94.50 FL
5	1		*WATER PUMP	Scratched	1,480.00 F	*1,480.00 FL
6	1		*OIL FILTER HOUSING	Cracked	800.00 F	*800.00 FL
7	1		*BELT:FOR WATER PUMP MD O530 CITARO BUS	Cut	103.15 F	*103.15 FL
8	1		*BUMPER :REAR CENTRE ,FOR MB CITARO O530	Cracked	1,791.33 F	*1,791.33 FL
9	1		*BUMPER :REAR ,LH ,FOR MB CITARO O530	Cracked	837.84 F	*837.84 FL
10	1		*REAR MEMBER SUB-ASSY RR	Bent	2,171.70 F	*2,171.70 FL
11	1		*STICKER SMRT	Necessary	75.00 FS	*75.00 FS
12	1		*STICKER 60KM/H	Necessary	5.00 FS	*5.00 FS
13	1		*COOLANT :ANTIFREEZE (60L/DR)-MB OC500	Necessary	871.25 FS	*871.25 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,283.67	15,064.58
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	1,411.33
Total Parts (\$)	15,283.67	13,653.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	2,650.00	2,120.00
2	SPRAY PAINT	New	956.00	694.00
3	TOWING CHARGE	New	200.00	200.00
Gross Labour Cost (S\$)			3,806.00	3,014.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >