LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21007166/T1TF3E2

Date: 02/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100419744

Claimant Vehicle ORDINAL AND AND FORCE AND FOR

No: SBS6604U Insured Vehicle No: SDL5666K

Date of Loss: 25/06/2021 Nature of Claim: TP Claim No: 4591901258SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBS6604U

 Make & Model:
 MERCEDES-BENZ CITARO 0530, 6.4 D (A)
 Engine No:
 90292609015969

 Reg. Date:
 03/01/2013 (Man. Year: 2012)
 Chassis No:
 WEB62808323124570

Colour: Multi-colour Odometer: 587106 km

Engine Capacity: 6374 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	932.00	932.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	580.00	580.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,512.00	1,512.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	105.84	105.84	0.00	0.00
Nett Amount (S\$)	1,617.84	1,617.84	0.00	0.00

INSPECTION

Date of Assignment: 30/06/2021

Date Inspected: 01/07/2021 Inspected At: 1470 BEDOK NORTH AVE 4

Sbs Transit Ltd (Bedok) (HQ) 1470 BEDOK NORTH AVE 4

Singapore 489946

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*CLAMPING PIECE;TRAILER COUPLING JAW	Broken	4.00 F	*4.00 F
2	1	*BUMPER CENTRE.REAR BUMPER COMPL	Cracked	813.00 F	*813.00 F
3	1	*JOINT COVER.REAR BUMPER	Deformed	115.00 F	*115.00 F
F=Fra	anchise part.		Total Parts (S\$)	932.00	932.00
		Report was unsubmitted during thi	s print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>			
1 CONTRACTOR LABOUR	New	580.00	580.00
	Gross Labour Cost (S\$)	580.00	580.00
Report v	vas unsubmitted during this print-out.		

< END OF ESTIMATES >