



Your Ref: S1M0386Y

Date: 26<sup>th</sup> July 2021

Our Ref: CS3/ASM21004824/Etce2-1

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Yu Dominic Yishan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJT 7541K**

**INSURED VEHICLE: SHA 4011S**

**ACCIDENT DATE: 14/04/2021**

We thank you for your instruction on 30/06/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJT 7541K from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SJT 7541K and SHA 4011S.
- c) Final Repair Bill of SJT 7541K from M/s A-Tec Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of SJT 7541K.

Pre-Repair Inspection Date : 19/04/2021 at M/s A-Tec Automotive Pte Ltd, 8 Kaki Bukit Ave 4 #05-27 Premier, Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

|                      |                      |
|----------------------|----------------------|
| Registration Number  | : SJT 7541K          |
| Make & Model         | : Toyota Wish 1.8X A |
| Year of Registration | : 2009               |
| Chassis Number       | : ZGE200021096       |
| Engine Capacity      | : 1797 cc            |

- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.