

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007167/BEA3Q2
Date: 29/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900263157
Claimant Vehicle No :	SML3771X	Insured Vehicle No :	GBJ1344A
Date of Loss:	27/06/2021	Nature of Claim:	TP
		Claim No:	0784233139SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML3771X	Engine No:	FB20YF37941
Make & Model:	SUBARU FORESTER, 2.0 I-L EYESIGHT AWD CVT (A)	Chassis No:	JF1SK7KL5KG007008
Reg. Date:	17/05/2019 (Man. Year: 2018)	Odometer:	45928 km
Colour:	Black		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,985.52	3,749.76	5,235.76	58.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	1,660.00	1,920.00	53.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,565.52	5,409.76	7,155.76	56.95
Approved Total (Overridden) (S\$)		4,300.00		

(S\$)	12,565.52	4,300.00	8,265.52	65.78
+ GST 7.00/7.00% (S\$)	879.59	301.00	578.59	65.78
Nett Amount (S\$)	13,445.11	4,601.00	8,844.11	65.78
+ Car Rental (10.0 x S\$140.00/day) (S\$)		1,400.00		
Nett Liability (S\$)		6,001.00		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 01/07/2021

Date Inspected: 01/07/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Ms Car Auto Pte Ltd (HQ)
 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
 Singapore 415875

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	1,292.00 FL	*1,292.00 FL
2	1		*REAR BOOT EMBLEM -SUBARU	Necessary	55.60 FL	*55.60 FL
3	1		*REAR BOOT EMBLEM -FORESTER	Necessary	59.40 FL	*59.40 FL
4	1		*REAR BOOT LOGO	Necessary	84.20 FL	*84.20 FL
5	1		*REAR BOOT LOCK	Not Damaged	196.00 FL	*- FL
6	1		*REAR BOOT W/STRIP	Torn	166.90 FL	*166.90 FL
7	2		*REAR BOOT HINGE L+R	Not Damaged	134.00 FL	*- FL
8	2		*REAR BOOT DAMPER L+R	Not Damaged	186.00 FL	*- FL
9	1		*REAR BOOT INNER TRIM	Broken	342.00 FL	*342.00 FL
10	10		*REAR BOOT INNER TRIM CLIP	Necessary	50.00 FL	*30.00 FL
11	1		*REAR BOOT W/S GLASS MOULDING	Necessary	117.00 FL	*117.00 FL
12	1		*REAR BUMPER	Broken	863.00 FL	*863.00 FL
13	1		*REAR BUMPER RETAINER L+R	Necessary	78.00 FL	*78.00 FL
14	1		*REAR BUMPER BRACKET L+R	Necessary	114.60 FL	*114.60 FL
15	1		*REAR BUMPER TOWING CAP	Not Damaged	76.50 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	589.00 FL	*320.00 FL
17	1		*REAR BUMPER SPONGE	No such part	176.00 FL	*- FL
18	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
19	2		*REAR BUMPER REFLECTOR L+R	Not Damaged	96.00 FL	*- FL
20	1		*TAIL LAMP L+R	N/S Broken	1,424.00 FL	*562.50 FL
21	2		*TAIL LAMP PANEL L+R	Not Damaged	428.00 FL	*- FL
22	4		*TAIL LAMP CLIP L+R	Necessary (2 PCS ONLY)	20.00 FL	*20.00 FL
23	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	126.80 FL	*- FL
24	1		*REAR END PANEL	Repair	553.00 FL	*- FL
25	1		*REAR END PANEL TOP GARNISH	Broken	192.00 FL	*192.00 FL
26	2		*REAR END PANEL TOP GARNISH CLIP	Necessary	10.00 FL	*10.00 FL
27	2		*SPARE WHEEL PANEL SIDE FOAM L+R	Not Damaged	342.00 FL	*- FL
28	1		*REAR EXHAUST PIPE	Not Damaged	1,253.40 FL	*- FL
29	1		*SET REAR EXHAUST PIPE CHROME	Not Damaged	362.00 FL	*- FL
30	2		*REAR EXHAUST PIPE MOUNTING	Not Damaged	68.00 FL	*- FL
31	1		*REAR EXHAUST PIPE GASKET	Not Damaged	32.00 FL	*- FL
32	1		*REAR EXHAUST PIPE HEAT SEAL	Not Damaged	182.00 FL	*- FL
33	2		*REVERSE SENSOR	Scratched	560.00 FS	*200.00 FS
34	1		*REAR BOOT W/S GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
35	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR NUMBER PLATE	Not Damaged	50.00 FS	*- FS
37	1		*REVERSE CAMERA	Not Damaged	400.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					10,929.40	4,617.20
- List Item Discount on L Items 20.00/20.00% (\$)					1,943.88	867.44
Total Parts (\$)					8,985.52	3,749.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO R&R ACCIDENT DAMAGE PARTS .TO CUT/WELD ,KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	1,500.00	800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,400.00	600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	0.00
4	TO R&R REAR BOOT W/S GLASS	New	140.00	120.00
5	TO R&R REAR BOOT MECHANISM	New	140.00	80.00
6	TO R&R REVERSE SENSOR AND CHECK FUNCTION	New	100.00	60.00
7	TO R&R REAR EXHAUST PIPE SYSTEM	New	180.00	0.00
Gross Labour Cost (S\$)			3,580.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >