

6/30/2021

Repairer Estimates


GOLDBELL
ENGINEERING

 Industrial Vehicles.
 20,000 Served. And Counting.
GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg No. 198003963G

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	XE4617J
Policy No:	DMCVSNW00011352100	Date of Loss:	24/06/2021
Vehicle Reg. No.:	XE4617J	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SAT.S PTE. LTD.		
Driver:	KARUPPIAH PERIYAKARUPPAN		

Make/Model:	MITSUBISHI FUSO SUPER GREAT FV, 12.9 D FV51JKM4RDEA (M)	Vehicle Reg. Date:	24/01/2019
Vehicle Colour:	WHITE		
Engine No:	470912C0357814	Chassis No:	FV70HJA00074
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location: **GOLDBELL ENGINEERING PTE LTD (TUAS)**

COST OF CLAIMS	Amount
Parts	12,756.85
Miscellaneous Items	375.00
Labour	5,800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	18,931.85
+ GST 7.00% (\$\$)	1,325.23
Nett Amount (\$\$)	20,257.08

This claim is handled by: CHONG KAI LING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 28 Jun 2021)**Parts:** N/A MITSUBISHI FUSO SUPER GREAT FV 12.9 D FV51JKM4RDEA (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Goldbell Engineering Pte Ltd/XE4617J/28/06/2021 18:21**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FORNT PANEL / <i>DD</i>	0.00	0.00	*2,440.13 F
2	1		*MARK, FUSO / <i>NEC</i>	0.00	0.00	*319.10 F
3	1		*MARK, 3-DIA / <i>NEC</i>	0.00	0.00	*145.54 F
4	1		*EMBLEM, SUPER GREAT / <i>NEC</i>	0.00	0.00	*51.00 F
5	1		*GRILLE ASSY, RADIATOR / <i>BR</i>	0.00	0.00	*575.39 F
6	1		*GRILLE ASSY, FRT UNDER / <i>DD</i>	0.00	0.00	*182.40 F
7	1		*PANEL, CAB FR CORNER, RH / <i>BR</i>	0.00	0.00	*564.77 F
8	1		*SEAL, DOOR OPENING RH / <i>?</i>	0.00	0.00	*65.70 F
9	1		*SHIELD, C/PNL LOWER LH (BEZEL) / <i>X</i>	0.00	0.00	*30.91 F
10	1		*SHIELD, C/PNL LOWER RH (BEZEL) / <i>TN</i>	0.00	0.00	*52.55 F
11	1		*BUMPER, FRT / <i>BT</i>	0.00	0.00	*2,645.41 F
12	1		*BEZEL, HEADLAMP -RH / <i>BR</i>	0.00	0.00	*316.98 F
13	1		*BEZEL, HEADLAMP -LH / <i>X</i>	0.00	0.00	*316.98 F
14	1		*COVER, FR BUMPER -RH / <i>BR</i>	0.00	0.00	*125.28 F
15	1		*COVER, FR BUMPER -LH / <i>BR</i>	0.00	0.00	*125.28 F
16	1		*COVER, FR BUMPER CTR / <i>MIS</i>	0.00	0.00	*359.47 F
17	1		*PROTECTOR, STEP LWR LH / <i>CRU</i>	0.00	0.00	*122.08 F
18	1		*PROTECTOR, STEP LWR RH / <i>CRU</i>	0.00	0.00	*117.91 F
19	2	1	*BRACKET, FR FOG LAMP / <i>(R4) BT</i>	0.00	0.00	*15.08 F
20	1		*STAY, HEADLAMP -LH / <i>X</i>	0.00	0.00	*340.22 F
21	1		*STAY, HEADLAMP -RH / <i>?</i>	0.00	0.00	*340.22 F
22	1		*PROTECTOR, STEP UPPER / <i>CNT</i>	0.00	0.00	*144.43 F
23	1		*HEADLAMP ASSY LH / <i>?</i>	0.00	0.00	*1,004.36 F
24	1		*HEADLAMP ASSY RH / <i>BR</i>	0.00	0.00	*1,004.36 F
25	1		*LAMP ASSY, FOG, FR LH / <i>X</i>	0.00	0.00	*346.40 F
26	1		*LAMP ASSY, FOG, FR RH / <i>BR</i>	0.00	0.00	*346.40 F
27	1		*OIL COOLER / <i>DD</i>	0.00	0.00	*658.50 F

F=Franchise part.

Total Parts (S\$)**12,756.85**

Goldbell Engineering Pte Ltd/XE4617J/28/06/2021 18:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

6/30/2021

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 COMPANY STICKER
2 1 FRONT NUMBER PLATE

222 350.00
25.00

Sub Total (\$\$) 375.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC
2 TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK
3 TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC

New

3000

3,600.00

New

150

200.00

New

1950

2,000.00

Gross Labour Cost (\$\$) 5,800.00

Goldbell Engineering Pte Ltd/XE4617J/28/06/2021 18:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve CLKK)
30/6/21, 12:00pm



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OD - M AL
EXPERI - \$1500
5 dys
PIP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: