

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007172/DQCN2**Date:** 17/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00068092100

**Claimant Vehicle
No :** GBE6925S**Insured Vehicle
No :** YQ3846X

Date of Loss: 25/06/2021

Nature of Claim: TP

Claim
No: SNM21D203571/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBE6925S**

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2582638

Reg. Date: 08/03/2016 (Man. Year: 2015)

Chassis No: JTFAT35Y50K205868

Colour: Silver

Odometer: 170010 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R12C (D)

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5/5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,457.28	1,466.17	11,991.11	89.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,300.00	1,140.00	6,160.00	84.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,757.28	2,606.17	18,151.11	87.44
Approved Total (Overridden) (\$\$)		2,050.00		
(\$\$)	20,757.28	2,050.00	18,707.28	90.12
+ GST 7.00/7.00% (\$\$)	1,453.01	143.50	1,309.51	90.12
Nett Amount (\$\$)	22,210.29	2,193.50	20,016.79	90.12

INSPECTION

Date of Assignment: 29/06/2021

Date Inspected: 01/07/2021 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Dec 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE6925S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	3		*REAR TAILGATE HINGE	Damaged	308.10 FL	*308.10 FL
2	2		*REAR TAILGATE LOCK LH/RH	Not Necessary	434.62 FL	*- FL
3	2		*REAR TAILGATE LOCK BRACKET LH/RH	Not Necessary	214.40 FL	*- FL
4	2		*REAR TAILGATE STOPPER LH/RH	Serviceable	143.56 FL	*- FL
5	2		*REAR TAILGATE STOPPER BRACKET LH/RH	Serviceable	264.18 FL	*- FL
6	1		*REAR TAILGATE TOYOTA STICKER	Necessary	159.00 FL	*159.00 FL
7	2		*REAR SIDE GATE LH/RH	Not Necessary	4,909.44 FL	*- FL
8	2		*TAIL LAMP LH/RH	Not Necessary	907.40 FL	*- FL
9	2		*TAIL LAMP BRACKET LH/RH	Not Necessary	271.64 FL	*- FL
10	1		*REAR END PANEL	Dented	1,074.59 FL	*595.00 FL
11	1		*REAR FLOOR PANEL	Not Necessary	2,880.90 FL	*- FL
12	2		*CHASSIS BRACKET	Not Necessary	629.04 FL	*- FL
13	1		*REAR NO PLATE LAMP	Not Necessary	107.20 FL	*- FL
14	1		*SPARE TYRE BRACKET	Not Necessary	498.56 FL	*- FL
15	1		*SPARE TYRE BOLT	Not Necessary	310.80 FL	*- FL
16	1		*SPARE TYRE HOLDER	Not Necessary	541.92 FL	*- FL
17	1		*REAR EXHAUST PIPE	Not Necessary	1,345.29 FL	*- FL
18	1		*REAR EXHAUST MOUNTING	Not Necessary	182.40 FL	*- FL
19	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
20	1		*FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
21	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
22	1		*70KM STICKER	Necessary	50.00 FS	*20.00 FS
23	1		*TAILGATE 13 PAX STICKER	Necessary	50.00 FS	*20.00 FS
24	1		*REAR TAILGATE (50%)	Dented	1,634.25 FS	*569.60 FS
25	1		*REAR TAILGATE DYNA STICKER	Necessary	75.75 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,253.04	1,731.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,795.76	265.53
Total Parts (\$\$)	13,457.28	1,466.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR REAR METAL DECK TO FACILITATE REPAIRS	New	1,800.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	500.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	150.00	0.00
6	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
Gross Labour Cost (\$)			7,300.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >