

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I		Ref:	CS3/ASM21007174/Vtce2		
	8 SHENTON WAY 068811		Date:	12/07/2021		
	ATTN: KHOR SAW	THENG		Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 482B	Veh. Inspected	l	GBC 9764E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03CPZ	Excess (\$)		0.00	
	Assign From	KHOR SAW THENG	Assign Date		30/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN NV350 2.5 5MT	c.c		2488	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	JN1MC2E26Z0001589	Colour		SILVER	
	Odometer	206991 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	TRIANGLE		5 mm	
	L/H Front Tyre	195 R15	TRIANGLE		5 mm	
	R/H Rear Tyre	195 R15	TRIANGLE		5 mm	
	L/H Rear Tyre	195 R15	TRIANGLE		5 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
5.	General Information					
	Accident Date	29/06/2021	Inspect Date /	Time	30/06/2021 (12:30 PM)	
	Survey held at	urvey held at GARAGE 13 PTE LTD				
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.					
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					

Report Ref No. CS3/ASM21007174/Vtce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser