

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21007176/AVCE2

**Date:** 01/11/2021

### REFERENCE

Insured/Claimant:	CHENG KHENG BOON	Policy No:	7210053600		
Date of Loss:	23/06/2021	Nature of Claim:	OD	Claim No:	4883643204SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL69G	Engine No:	HIDDEN
Make & Model:	AUDI E-TRON, SPORTBACK ADV 50 QUATTRO (A)	Chassis No:	WAUZZZGE6MB032865
Reg. Date:	29/05/2021 (Man. Year: 2021)	Odometer:	1278 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$300,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	255/50 R20	Rear Tyre Size:	255/50 R20
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,188.00	3,363.76	28,824.24	89.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,972.00	2,272.00	5,700.00	71.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>40,160.00</b>	<b>5,635.76</b>	<b>34,524.24</b>	<b>85.97</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>39,560.00</b>	<b>5,035.76</b>	<b>34,524.24</b>	<b>87.27</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,769.20</b>	<b>352.50</b>	<b>2,416.70</b>	<b>87.27</b>
<b>Nett Amount (S\$)</b>	<b>42,329.20</b>	<b>5,388.26</b>	<b>36,940.94</b>	<b>87.27</b>

### INSPECTION

Date of Assignment:	30/06/2021		
Date Inspected:	29/06/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,724.00 FS	*- FS
2	2		*FRONT BUMPER LOWER SIDE TRIM - LH / RH	Not Necessary	116.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	631.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Damaged	222.00 FS	*177.60 FS
5	1		*FRONT RADIATOR GRILLE BRACKET - LH	Not Necessary	30.00 FS	*- FS
6	2		*FRONT BUMPER COVER - LH / RH	Not Necessary	70.00 FS	*- FS
7	2		*FRONT RADIATOR GRILLE FOAM	Not Necessary	246.00 FS	*- FS
8	1		*FRONT BUMPER PLASTIC FORM STRIP	Not Necessary	120.00 FS	*- FS
9	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	254.00 FS	*- FS
10	1		*FRONT BUMPER INNER GRILLE - CENTER	Cracked	153.00 FS	*122.00 FS
11	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	210.00 FS	*- FS
12	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	182.00 FS	*- FS
13	1		*FRONT BUMPER IMPACT PROTECTION (SILVER)	Not Necessary	807.00 FS	*- FS
14	2		*FRONT BUMPER SIDE SPOILER - LH / RH	Not Necessary	314.00 FS	*- FS
15	6		*FRONT RADIATOR AIR GUIDE - UPPER / LOWER CENTER - LH / RH	Not Necessary	420.00 FS	*- FS
16	1		*FRONT RADIATOR GRILLE	Cracked	2,086.00 FS	*1,668.80 FS
17	1		*FRONT RADIATOR GRILLE CAMERA COVER	Not Necessary	136.00 FS	*- FS
18	1		*FRONT RADIATOR GRILLE CAMERA BRACKET	Not Necessary	93.00 FS	*- FS
19	1		*FRONT RADIATOR GRILLE CAMERA SECURING PLATE	Not Necessary	84.00 FS	*- FS
20	1		*FRONT RADIATOR GRILLE LOGO COVER	Not Necessary	62.00 FS	*- FS
21	1		*FRONT RADIATOR GRILLE CLOSING ELEMEMENT (GREY)	Not Necessary	221.00 FS	*- FS
22	2		*FRONT RADIATOR GRILLE COVER (GREY) - LH / RH	Not Necessary	275.00 FS	*- FS
23	1		*FRONT RADIATOR GRILLE CAMERA	Not Necessary	906.00 FS	*- FS
24	1		*SET FRONT BUMPER WIRING	Not Necessary	577.00 FS	*- FS
25	1		*FRONT BUMPER TEMPERATURE SENSOR	Not Necessary	59.00 FS	*- FS
26	1		*FRONT BUMPER CROSS MEMBER - LOWER	Not Necessary	425.00 FS	*- FS
27	1		*FRONT BUMPER CARRIER	Not Necessary	1,362.00 FS	*- FS
28	1		*FRONT BUMPER BRACKET	Not Necessary	430.00 FS	*- FS
29	1		*FRONT RADIATOR GRILLE COVER - TOP / BOTTOM	Top Cracked	210.00 FS	*84.00 FS
30	2		*FRONT RADIATOR GRILLE BRACKET - LH / RH	Not Necessary	154.00 FS	*- FS
31	1		*WARNING SIGN STICKER	Necessary	19.00 FS	*14.80 FS
32	2		*FRONT PARKING AID SENSOR - INNER (NPA)	Not Necessary	0.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
34	2		*FRONT BUMPER SPOILER - LH / RH	Not Necessary	190.00 FS	*- FS
35	2		*FRONT HEADLIGHT - LH / RH	Not Necessary	16,284.00 FS	*- FS
36	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,030.00 FS	*827.20 FS
37	1		*FRONT NO. PLATE	Dented	60.00 FS	*60.00 FS
38	1		*SUNDRIES	Necessary	300.00 FS	*10.56 FS
39	2		*E-TRON EMBLEM	Not Necessary	212.00 FS	*- FS
40	1		*FORM PART (Supplementary)	Deformed	134.00 FS	*107.20 FS
41	1		*FRONT AIR GUIDE-UPPER (Supplementary)	Damaged	77.00 FS	*61.20 FS
42	1		*WASHER HOSE (Supplementary)	Cut	96.00 FS	*76.40 FS
43	1		*LICENCE PLATE HOLDER (Supplementary)	Deformed	193.00 FS	*154.00 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>32,188.00      3,363.76</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,000.00	600.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	4,500.00	1,000.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,972.00</b>	<b>2,272.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >