

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007187/AQCEN2**Date:** 30/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00009702100

Claimant Vehicle No : SLK5616R **Insured Vehicle No :** ES100K

Date of Loss: 28/06/2021 Nature of Claim: TP Claim No: SNM21D203619/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK5616R**

Make & Model: MAZDA 3, 1.5 (A) Engine No: P520423693

Reg. Date: 20/01/2017 (Man. Year: 2016) Chassis No: JM6BN22A8H0137791

Colour: Bronze Odometer: 203637 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Crucero 6 mm Rear Left Side: Crucero 6 mm

Front Right Side: Crucero 6 mm Rear Right Side: Crucero 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,336.00	6,077.68	9,258.32	60.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,140.00	1,110.00	3,030.00	73.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,476.00	7,187.68	12,288.32	63.09
Approved Total (Overridden) (\$\$)		5,300.00		
(\$\$)	19,476.00	5,300.00	14,176.00	72.79
+ GST 7.00/7.00% (\$\$)	1,363.32	371.00	992.32	72.79
Nett Amount (\$\$)	20,839.32	5,671.00	15,168.32	72.79

INSPECTION

Date of Assignment: 22/09/2021

Date Inspected: 30/06/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Sep 2021)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK5616R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,089.00 FL	*1,089.00 FL
2	1		*FRONT BUMPER TOP PAD	Not Necessary	458.00 FL	*- FL
3	1		*FRONT BUMPER TOP PAD BASE	Not Necessary	286.00 FL	*- FL
4	1		*FRONT BUMPER TOWING COVER	Not Necessary	45.60 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER	O/s Damaged	197.00 FL	*98.50 FL
6	1		*FRONT BUMPER LOWER ABSORBER	Deformed	308.50 FL	*308.50 FL
7	1		*FRONT BUMPER LOWER SUPPORT BEAN RH	Not Necessary	215.00 FL	*- FL
8	1		*FRONT BUMPER LOWER SIDE SUPPORT RH	Not Necessary	192.30 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	750.10 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT GARNISH	Not Necessary	285.60 FL	*- FL
11	1		*FRONT BUMPER UNDER COVER	Torn	189.20 FL	*189.20 FL
12	1		*FRONT FOG LAMP RH	Cracked	321.00 FL	*321.00 FL
13	1		*FRONT FOG LAMP GARNISH RH	Deformed	277.80 FL	*68.00 FL
14	1		*WIPER WASHER TANK	Deformed	169.30 FL	*169.30 FL
15	1		*WIPER WASHER TANK MOTOR	Not Necessary	277.40 FL	*- FL
16	1		*HEAD LAMP RH	Cut	3,289.00 FL	*3,289.00 FL
17	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	157.60 FL	*- FL
18	1		*FRONT GRILLE	Cracked	970.10 FL	*450.00 FL
19	1		*FRONT GRILLE CHROME MOULDING RH	Cracked	276.40 FL	*198.00 FL
20	1		*FRONT GRILLE EMBLEM	Not Necessary	104.90 FL	*- FL
21	1		*FRONT GRILLE TOP GARNISH	Not Necessary	320.50 FL	*- FL
22	1		*FRONT GRILLE SUPPORT BRACKET RH	Damaged	154.00 FL	*154.00 FL
23	1		*FRONT GRILLE SUPPORT BRACKET PIN (2 Pcs)	Damaged	178.00 FL	*89.00 FL
24	1		*FRONT SUPPORT TOP PANEL RH	Not Necessary	448.00 FL	*- FL
25	1		*FRONT SUPPORT PANEL	Not Necessary	886.90 FL	*- FL
26	1		*RADIATOR AIR GUIDE	Not Necessary	135.30 FL	*- FL
27	1		*A/C CONDENSER	Not Necessary	976.30 FL	*- FL
28	1		*RADIATOR	Not Necessary	1,527.50 FL	*- FL
29	1		*FRONT FENDER RH	Dented	665.00 FL	*665.00 FL
30	1		*FRONT FENDER TOP GARNISH RH	Not Necessary	154.00 FL	*- FL
31	1		*FRONT FENDER INNER SHIELD RH	Torn	221.10 FL	*221.10 FL
32	1		*FRONT ABSORBER RH	Not Necessary	556.70 FL	*- FL
33	1		*FRONT LOWER ARM RH	Not Necessary	457.60 FL	*- FL
34	1		*FRONT KNUCKLE ARM RH	Not Necessary	650.90 FL	*- FL
35	1		*FRONT WHEEL BEARING RH	Not Necessary	415.90 FL	*- FL
36	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
37	1		*FRONT BUMPER TOP PAD RIVET	Not Necessary	70.00 FS	*- FS
38	1		*FRONT BUMPER UNDER COVER CLIP	Not Necessary	50.00 FS	*- FS
39	1		*FRONT GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
40	1		*FRONT FENDER TOP GARNISH CLIP	Not Necessary	40.00 FS	*- FS
41	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	40.00 FS	*30.00 FS
42	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*RADIATOR COOLANT	Not Necessary	70.00 FS	*- FS
44	1		*FRONT TYRE LH	Not Necessary	400.00 FS	*- FS
45	1		*WHEEL RIM	Cut	400.00 FS	*150.00 FS

Report was unsubmitted during this print-out.

9/30/21, 12:59 PMAdjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					18,857.50	7,539.60
- List Item Discount on L Items 20.00/20.00% (S\$)					3,521.50	1,461.92
Total Parts (S\$)					15,336.00	6,077.68
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,300.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,500.00	400.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	60.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	250.00	0.00
5	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	600.00	0.00
6	TO CHECK FOUR WHEEL ALIGNMENT	New	100.00	80.00
7	REMOVE AND INSTALL RADIATOR ASSY,PERFORMED RADIATOR PRESSURE TEST	New	150.00	0.00
8	REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	New	180.00	0.00
Gross Labour Cost (\$\$)			4,140.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >