

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III21007189/UVF3E2**Date:** 05/07/2021**REFERENCE**

Insured/Claimant:	SEET TZE MENG,AUGUSTINE	Policy No:	D18MPC0002227_02	
Date of Loss:	17/06/2021	Nature of Claim:	OD	Claim No: N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SME9099B</b>	Engine No:	L15B4279831
Make & Model:	HONDA FREED, 1.5 (A)	Chassis No:	GB51058986
Reg. Date:	05/10/2018 (Man. Year: 2017)	Odometer:	101187 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,884.96	2,810.96	2,074.00	42.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	1,830.00	1,880.00	50.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,594.96</b>	<b>4,640.96</b>	<b>3,954.00</b>	<b>46.00</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,700.00</b>		
<b>- Excess (\$\$)</b>	600.00	600.00	0.00	0.00
<b>Nett Amount (\$\$)</b>	<b>7,994.96</b>	<b>3,100.00</b>	<b>4,894.96</b>	<b>61.23</b>

**INSPECTION**

Date of Assignment:	30/06/2021		
Date Inspected:	21/06/2021	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2021)
<b>Parts:</b>	M1-MPV	HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SME9099B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE DOOR	Dented	1,358.00 FL	*1,204.30 FL
2	1		*SET REAR WINDSCREEN INNER SEAL	Necessary	74.10 FL	*74.10 FL
3	1		*REAR WINDSCREEN INNER DAM RUBBER	Necessary	54.00 FL	*54.00 FL
4	1		*REAR WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
5	1		*TAIL GATE DOOR FREED EMBLEM	Necessary	69.30 FL	*69.30 FL
6	1		*TAIL GATE DOOR I-VTEC EMBLEMS	Necessary	36.60 FL	*36.60 FL
7	1		*TAIL GATE DOOR M LOGO	Necessary	38.20 FL	*38.20 FL
8	1		*TAIL GATE DOOR N/S REFLECTOR (HYBRID TYRE)	Not Necessary	429.50 FL	*- FL
9	1		*TAIL GATE DOOR WEATHERSTRIP	Not Necessary	185.30 FL	*- FL
10	1		*SET TAIL GATE DOOR TRIM BOARD CLIPS	Necessary	118.00 FL	*59.00 FL
11	1		*N/S TAIL LAMP ASSY	Grazed	750.80 FL	*750.80 FL
12	2		*N/S TAIL LAMP CLIPS STOPPER	Necessary	11.80 FL	*11.80 FL
13	1		*REAR BUMPER	Distorted	809.80 FL	*778.40 FL
14	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
15	1		*REAR BUMPER N/S SIDE RETAINER	Bent	28.60 FL	*28.60 FL
16	1		*REAR BUMPER N/S TOP RETAINER	Bent	31.20 FL	*31.20 FL
17	1		*REAR BUMPER N/S SIDE BRACKET CLIPS	Necessary	6.80 FL	*6.80 FL
18	1		*REAR BUMPER DAMPER	Not Necessary	68.30 FL	*- FL
19	1		*SET REAR BUMPER REFLECTER	Broken	136.60 FL	*136.60 FL
20	1		*SET REAR BUMPER SIDE SPOILER	Damaged	86.00 FL	*86.00 FL
21	1		*N/S TAIL LAMP PANEL	Repair	158.30 FL	*- FL
22	1		*REAR N/S FENDER	Repair	1,209.10 FL	*- FL
23	10		*REAR N/S FENDER INNER GARNISH CLIPS	Necessary	59.00 FL	*59.00 FL
24	1		*SET REVERSE SENSOR	Serviceable	287.90 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,094.20</b>	<b>3,503.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,209.24	692.74
<b>Total Parts (\$\$)</b>	<b>4,884.96</b>	<b>2,810.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	30.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS	New	150.00	120.00
3	TO REMOVE & REFIX TAIL GATE DOOR TOP SPOILER & REPUMP SEALANT	New	150.00	50.00
4	TO TRANSFER TAIL GATE DOOR INNER LOCK, TRIM BOARD, WIPER MOTOR, GARNISH, SHOCK ABSORBER, HINGE, THIRD BRAKE LIGHT, GARNISH & NECESSARY PARTS INTO NEW TAIL GATE DOOR	New	200.00	120.00
5	TO REMOVE & REFIX CARPET, FLOOR MAT, GARNISH, FLOOR BOARD COVER, TOOL SET, SPARE TYRE & NECESSARY PARTS	New	120.00	60.00
6	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	90.00	0.00
7	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT REAR N/S FENDER, TAIL LAMP PANEL, REAR END PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	1,300.00	600.00
8	TO PUTTY & RESPRAY PEARL WHITE COLOUR ON ALL AFFECTED ACCIDENT PARTS	New	1,650.00	850.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,710.00</b>	<b>1,830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >