

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI21007213/KQF3Q2**Date:** 12/07/2023REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG20014126
Claimant Vehicle No :	GX8385C	Insured Vehicle No :	GBJ11S
Date of Loss:	26/06/2021	Nature of Claim:	TP
		Claim No:	CDMCG21001175

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX8385C	Engine No:	5L5480898
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFUF34Y103002850
Reg. Date:	04/10/2004 (Man. Year: 2004)	Odometer:	407532 km
Colour:	Silver		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155R12X8 (D)
Front Left Side:	Condor 9 mm	Rear Left Side:	Condor 5/5 mm
Front Right Side:	Condor 9 mm	Rear Right Side:	Condor 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,211.90	1,334.67	3,877.23	74.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,710.00	1,100.00	4,610.00	80.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,921.90	2,434.67	8,487.23	77.71
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	10,921.90	1,950.00	8,971.90	82.15
+ GST 8.00/8.00% (S\$)	873.75	156.00	717.75	82.15
Nett Amount (S\$)	11,795.65	2,106.00	9,689.65	82.15

INSPECTION

Date of Assignment:	01/07/2021	
Date Inspected:	05/07/2021 Inspected At:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Jul 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX8385C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,116.70 FL	*1,116.70 FL
2	2		*GUARD FRAME BRACKET	Repair	129.60 FL	*- FL
3	1		*REAR LIGHT RH	Cracked	232.10 FL	*232.10 FL
4	1		*REAR LIGHT LH	Cracked	232.10 FL	*232.10 FL
5	1		*SIDE PANEL RH	Repair	1,116.70 FL	*- FL
6	1		*SIDE PANEL LH	Repair	1,116.70 FL	*- FL
7	1		*REAR CROSS SILL	Repair	585.80 FL	*- FL
8	1		*TAILGATE CHAIN ASSY RH	Repair	69.90 FL	*- FL
9	1		*TAILGATE CHAIN ASSY LH	Repair	69.90 FL	*- FL
10	1		*REAR LAMP BRACKET RH	Repair	51.50 FL	*- FL
11	1		*REAR LAMP BRACKET LH	Repair	51.50 FL	*- FL
12	1		*REAR NUMBER PLATE HOLDER	Serviceable	108.10 FL	*- FL
13	1		*EXHAUST HANGER	Serviceable	38.00 FL	*- FL
14	1		*SIDE SILL RH	Repair	585.80 FL	*- FL
15	1		*SIDE SILL LH	Repair	585.80 FL	*- FL
16	1		*EXHAUST END	Repair	499.00 FL	*- FL
17	1		*CAR NUMBER PLATE	Dented	50.00 FS	*25.00 FS
18	1		*TOYOTA TAILGATE STICKER	Necessary	100.00 FS	*100.00 FS
19	1		*STICKER 70KM/H	Necessary	60.00 FS	*12.00 FS
20	1		*STICKER 13 PAX	Necessary	60.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,859.20	1,729.90
- List Item Discount on L Items 25.00/25.00% (\$)	1,647.30	395.23
Total Parts (\$)	5,211.90	1,334.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI-RUST COATING	New	160.00	30.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	2,800.00	600.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	2,200.00	450.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECL ELECTRICAL WIRING	New	150.00	20.00
5	REMOVE AND REPLACEMENT OF EXHAUST PIPE TO FACILITATE REPAIR	New	250.00	0.00
6	REALIGN OF EXHAUST	New	150.00	0.00
Gross Labour Cost (S\$)			5,710.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >