

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1013X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$138.10	SERVICEABLE	276.20	-
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	DEFORMED	155.00	155.00
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	SERVICEABLE	98.80	-
1	REAR BUMPER FOG LAMP	SERVICEABLE	201.50	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	225.00	-
1	REAR SMART KEY ANTENNA	SERVICEABLE	40.50	-
	LESS 20% DISCOUNT		-464.89	-125.65
			1,859.56	502.60
	NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (N)	SERVICEABLE	180.00	-
1	REAR NO PLATE W/TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-23.50	-5.50
			211.50	49.50
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	350.00
	SPRAY PAINTING.		300.00	250.00
	R/I REVERSE SENSOR.		120.00	30.00
			820.00	630.00
_	GRAND TOTAL		2,941.06	1,232.10

Report Ref No. NS/INC21007214/Ntcn2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED) 1,232.10

Report Ref No. NS/INC21007214/Ntcn2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

The

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser