

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



NTUC INCOME INSURANCE CO-OPERATIVE LTD				NS/INC21007214/N	Vtcn2
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	13-07-2021 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FX 6600G	1	nspected	SHC 1013X
	Policy No.			 age (\$)	0.00
	Claim No.	MT/1135700-002	Exces	s (\$)	0.00
	Assign From		Assig	n Date	25/06/2021
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ G2	c.c		1580
	Engine No.	HIDDEN	Year o	f Reg.	2019
	Chassis No.	KMHC851CVKU164520	Colou	r	BLUE
	Odometer	189328	Steeri	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	WEST		5 mm
	L/H Front Tyre	195/65 R15	WEST		5 mm
	R/H Rear Tyre	195/65 R15	WEST		5 mm
	L/H Rear Tyre	195/65 R15	WEST		5 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	24/06/2021		tion Date	25/06/2021
	Survey held at				
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				