

ASS. REC. BY: Kenneth REF: CTZ/21007216/KT

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Fulco

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 282C

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 58K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLR 4484G Yr Regn: 08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or N/A

Make: Mit Canter C.C. 1590

Colour: White A/C: Insured / Std / Nil / NA

Sp. Reading: 50219 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: TMYSRCYIA GU 006921

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 8 mm Rear: 8 mm

R/Bal. 8 mm R/Bal. 8 mm


L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 26/6/21 D.O.I. 1/7/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Finalise offer at lump sum \$12,300, 21days

red: 9780.922; 44%

Time, File Pass to? ☐ : Prell. Report

Time, File Return to? ☐ : Final Report

Days Of Repair: 21

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S - RS - SI

Part Format: \_\_\_\_\_

Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Others: \_\_\_\_\_

TOTAL: \_\_\_\_\_

Repair Estimate


# Fulco Autocare Pte Ltd

176 Sin Ming Drive #03-02 Sin Ming Autocare Singapore 575721  
Tel: (65) 6552 0302 Fax: (65) 6552 0780 Email: admin@fulcoautocare.com

Make/Model: MITSUBISHI LANCER EX  
Engine/Chassis No.:  
Date of accident:  
Damaged area: Rear

*Not Withheld*  
*1/100 @ 12,300/1*  
*Recovery After Repair*

Date: 01/07/2021  
Claim Type: TP  
VRN: SLR4464G



*21 days*

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bootlid <i>899</i>	<i>R</i> 1	\$ 1,213.00	\$ 1,213.00
2	Bootlid inner trim	<i>Ref</i> 1	\$ 181.00	\$ 181.00
3	Bootlid hinge	<i>R</i> 2	\$ 67.00	\$ 134.00
4	Bootlid lock	<i>M</i> 1	\$ 159.00	\$ 159.00
5	Bootlid lock striker	<i>M</i> 1	\$ 65.00	\$ 65.00
6	Bootlid brake lamp	<i>R</i> 1	\$ 394.00	\$ 394.00
7	Bootlid release cable	<i>M</i> 1	\$ 53.00	\$ 53.00
8	Bootlid weatherstrip	<i>Ref/CM</i> 1	\$ 185.00	\$ 185.00
9	Licence plate lamp	<i>CR</i> 2	\$ 72.00	\$ 144.00
10	Bootlid "LANCER" emblem	<i>M</i> 1	\$ 57.00	\$ 57.00
11	Bootlid "MIVEC" emblem	<i>M</i> 1	\$ 49.00	\$ 49.00
12	Bootlid "MITSUBISHI" logo	<i>M</i> 1	\$ 61.00	\$ 61.00
13	Bootlid "C&C" emblem	<i>M</i> 1	\$ 42.00	\$ 42.00
14	Bootlid release switch	<i>M</i> 1	\$ 142.00	\$ 142.00
15	Bootlid lamp <i>C347</i>	<i>CR</i> 2	\$ 474.00	\$ 948.00
16	Bootlid lamp sponge seal	<i>M</i> 2	\$ 8.00	\$ 16.00
17	Rear bumper <i>818</i>	<i>R</i> 1	\$ 988.00	\$ 988.00
18	Rear bumper side retainer	<i>CR</i> 2	\$ 57.00	\$ 114.00
19	Rear bumper reinforcement <i>210</i>	<i>R</i> 1	\$ 576.00	\$ 576.00
20	Rear bumper reflector <i>C67</i>	<i>CR</i> 2	\$ 118.00	\$ 236.00
21	Taillamp <i>C356</i>	<i>CM</i> 2	\$ 589.00	\$ 1,178.00
22	Taillamp sponge seal	<i>MC</i> 2	\$ 8.00	\$ 16.00
23	Taillamp panel	<i>R</i> 2	\$ 147.00	\$ 294.00
24	Taillamp lower bracket	<i>CR</i> 2	\$ 33.00	\$ 66.00
25	End panel <i>506</i>	<i>R</i> 1	\$ 732.00	\$ 732.00
26	End panel top garnish	<i>M</i> 1	\$ 164.00	\$ 164.00
27	Spare tyre panel	<i>MT/BR</i> 1	\$ 895.00	\$ 895.00
28	Spare tyre top board	<i>CR</i> 1	\$ 127.00	\$ 127.00
29	Rear fender liner	<i>CR</i> 2	\$ 185.00	\$ 370.00
30	Rear bumper tow cover	<i>M</i> 1	\$ 76.00	\$ 76.00
31	Rear fender	<i>R</i> 2	\$ 899.00	\$ 1,798.00
32	Rear fender inner trim	<i>Reform/CM</i> 2	\$ 196.00	\$ 392.00
33	Rear windscreen moulding	<i>M</i> 1	\$ 165.00	\$ 165.00

*508.5 ~ 52.505 ~*



# Repair Estimate

34	Rear bumper lower cowl	1	\$ 236.00	\$ 236.00	X
35	Rear bumper support bracket	1	\$ 158.00	\$ 158.00	X
36	Rear bumper licence plate lamp garnish	1	\$ 145.00	\$ 145.00	X
37	Bootlid absorber	2	\$ 98.00	\$ 196.00	X
38	Parking sensor wire harness	1	\$ 213.00	\$ 213.00	X
39	Rear fender air vent	2	\$ 69.00	\$ 138.00	X
40	Rear windscreen glass	1	\$ 1,519.00	\$ 1,519.00	X
41	C pillar inner trim	2	\$ 198.00	\$ 396.00	X
42	Exhaust assy	1	\$ 873.00	\$ 873.00	X
43	Exhaust assy heatshield	1	\$ 153.00	\$ 153.00	X
44	Exhaust assy holder	2	\$ 45.00	\$ 90.00	X
45	Exhaust chrome tip	1	\$ 129.00	\$ 129.00	X
46	Rear speaker trim board	1	\$ 395.00	\$ 395.00	X
				<b>Subtotal</b>	<b>\$ 16,671.00</b>
				<b>List discount</b>	<b>10.00%</b>
				<b>Total</b>	<b>\$ 15,003.90</b>

Special nett items					
No.	Parts description		QTY	UNIT PRICE	AMOUNT
1	Rear fender inner trim clips	RM	12	\$ 4.50	\$ 54.00
2	Rear windscreen sealant	RM	1	\$ 120.00	\$ 120.00
3	Reverse sensor	RM	1	\$ 280.00	\$ 280.00
4	Bootlid inner trim clips	RM	10	\$ 4.50	\$ 45.00
5	Rear bumper clips	RM	10	\$ 4.50	\$ 45.00
6	Taillamp clips	RM	6	\$ 4.50	\$ 27.00
7	Bootlid lamp clips	RM	6	\$ 4.50	\$ 27.00
8	End panel sealant	RM	1	\$ 100.00	\$ 100.00
9	End panel top garnish clips	RM	6	\$ 4.50	\$ 27.00
10	Spare tyre floor panel sealant	RM	1	\$ 100.00	\$ 100.00
11	Rear fender cowl clips	RM	10	\$ 4.50	\$ 45.00
12	Rear licence plate & frame	RM	1	\$ 55.00	\$ 55.00
13	Reverse camera	NFP	1	\$ 350.00	\$ 350.00
14	Rear bumper lower cowl clips	RM	8	\$ 4.50	\$ 36.00
15	Spare tyre floor panel insulator	RM	1	\$ 150.00	\$ 150.00
16	Rear windscreen sealant solar film	RM	1	\$ 280.00	\$ 280.00
17	C pillar inner trim clips	RM	16	\$ 4.50	\$ 72.00
18	Rear speaker trim board clips	RM	12	\$ 4.50	\$ 54.00
19	Rear speaker	RM	2	\$ 180.00	\$ 360.00
20	Sundries	RM	1	\$ 50.00	\$ 50.00
Total					\$ 2,277.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	10	\$ 2,000.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00

# Repair Estimate

3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	0.5	\$	100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	8	\$	1,600.00
5	To rust proof all affected portions after repair.	0.5	\$	100.00
6	To remove and refit rear windscreen to facilitate repair work.	0.75	\$	150.00
7	To remove and refit rear cushion seat, backrest, interior upholstery, inner trim, inner garnish, floor carpet, mouldings to facilitate repair work.	1.25	\$	250.00
8	To align rear chassis frame and to conduct chassis alignment on Car-O-Liner.	1.5	\$	300.00
9	To remove and refit exhaust ass'y to facilitate repair work.	0.5	\$	100.00
10	To remove and refit fuel tank ass'y to facilitate repair work.	0.75	\$	150.00
Total labour			\$	4,800.00

500

1400

✓

1200

1200

2500

600

600

Estimate Grand Total	\$	22,080.90
----------------------	----	-----------

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: