



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1239L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER LOWER COVER	SCRATCHED	552.60	552.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	REAR BUMPER TOW COVER	SERVICEABLE	82.70	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	55.00	-
1	REAR BUMPER SIDE RETAINER/RH	SERVICEABLE	112.70	-
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-400.60	-258.30
			1,201.80	774.90
<u>SPECIAL NETT ITEMS</u>				
1	REAR FENDER ADVERTISEMENT RH (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	50.00	50.00
1	BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
			285.70	150.00
<u>LABOUR</u>				
	PANEL BEATING.		600.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	CHECK WIRING AND LIGHTING.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.		60.00	40.00
			1,320.00	640.00
GRAND TOTAL			2,807.50	1,564.90
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,564.90

Report Ref No. NS/INC21007218/R1vcn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.