



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5947K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER ASSY	SCRATCHED	430.90	430.90
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	HEADLAMP ASSY LH	CRACKED	1,993.65	1,993.65
1	FRT BUMPER BRACKET LH	SERVICEABLE	35.00	-
1	FRT BUMPER MOULDING	SCRATCHED	368.50	368.50
	LESS 20% DISCOUNT		-570.01	-563.01
			2,280.04	2,252.04
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAYPAINT.		300.00	250.00
	CHECK WIRING.		50.00	30.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
			800.00	630.00
	GRAND TOTAL		3,080.04	2,882.04
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,882.04

Report Ref No. NS/INC21007221/R1qcn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.