



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9442G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	SERVICEABLE	318.80	-
1	REAR BUMPER LOWER COVER-BLACK	SCRATCHED	552.60	552.60
1	REAR BUMPER SIDE RETAINER RH	SCRATCHED	112.70	112.70
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER EXTENSION RH	CUT	232.00	232.00
1	TAIL LAMP ASSY (UPPER) RH	CRACKED	557.90	557.90
1	TAIL LAMP ASSY (LOWER) RH	CRACKED	548.40	548.40
	LESS 25% DISCOUNT		-700.75	-621.05
			2,102.25	1,863.15
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTINGS.	NOT NECESSARY	40.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	60.00
			860.00	660.00
	<b>GRAND TOTAL</b>		<b>2,962.25</b>	<b>2,523.15</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>2,000.00</b>

Report Ref No. NS/INC21007223/R1tcn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.