

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG21007226/EGS3Q2

Date:

14/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100445544-05

Claimant Vehicle No : SKW4944Z**Insured Vehicle No :**

SKX8294J

Date of Loss: 30/06/2021

Nature of Claim:

TP

Claim No:

7464778638SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKW4944Z

Make & Model:

VOLKSWAGEN GOLF, 1.2 TSI (A)

Reg. Date:

30/10/2015 (Man. Year: 2015)

Colour:

White

Engine Capacity:

1395 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

Engine No:

CXS259074

Chassis No:

WVWZZZAUZFW356593

Odometer:

22268 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side:

Pirelli 5 mm

Rear Left Side:

Pirelli 5 mm

Front Right Side:

Pirelli 5 mm

Rear Right Side:

Pirelli 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,961.51	3,097.18	4,864.33	61.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,580.00	5,020.00	6,560.00	56.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,541.51	8,117.18	11,424.33	58.46
+ GST 7.00/7.00% (S\$)	1,367.91	568.20	799.71	58.46

Nett Amount (S\$)	20,909.42	8,685.38	12,224.04	58.46
		+ Loss of Use (8.0 x S\$80.00/day) (S\$)	640.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	9,327.38	

INSPECTION

Date of Assignment: 02/07/2021

Date Inspected: 02/07/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*INSCRIPTION BRIGHT CHROME REAR LOGO -GOLF	Not Necessary	80.16 FS	*- FS
2	1		*INSCRIPTION PURE WHITE /PO LOGO -BLUEMOTION	Not Necessary	83.25 FS	*- FS
3	1		*INSCRIPTION CHROME SHINE /LOGO-TSI	Not Necessary	84.47 FS	*- FS
4	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Repair	1,303.20 FS	*- FS
5	1		*REAR DIFFUSOR SATIN BLACK	Not Necessary	336.18 FS	*- FS
6	1		*BUMPER REAR REINFORCEMENT	Not Necessary	650.77 FS	*- FS
7	1		*ATTACHMENT STRIP REAR BUMPER CTR BRACKET	Not Necessary	69.96 FS	*- FS
8	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPRER)	Not Necessary	40.52 FS	*- FS
9	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPRER)	Not Necessary	40.52 FS	*- FS
10	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	40.52 FS	*- FS
11	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	40.52 FS	*- FS
12	2		*LICENSE PLATE LIGHT	Not Necessary	81.70 FS	*- FS
13	1		*COVER FOR BUMPER PRIMED FRT BUMPER	Dented	1,313.60 FS	*1,313.60 FS
14	1		*IMPACT BEAM FRT REINFORCEMENT	Not Necessary	683.62 FS	*- FS
15	1		*FOAM INSERT FRT BUMPER FOAM	Broken	45.29 FS	*45.29 FS
16	1		*SUPPORT PART BUMPER INNER BRACKET LH	Not Necessary	59.04 FS	*- FS
17	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	22.75 FS	*- FS
18	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	22.75 FS	*- FS
19	1		*RADIATOR GRILLE SATIN BLA	Cut	524.74 FS	*524.74 FS
20	1		*COOLING AIR GRILL SATIN B BUMPER CTR LOWER GRILLE	Crushed	149.05 FS	*149.05 FS
21	1		*GUIDE FRT BUMPER CTR BRACKET	Bent	51.97 FS	*51.97 FS
22	1		*SUPPORT FOR LOCK CARRIER	Broken	46.50 FS	*46.50 FS
23	1		*CROSS SUPPORT H/LAMP TOP PANEL LH	Not Necessary	38.96 FS	*- FS
24	1		*TWIN HALOGEN HEADLAMPS LH	Not Necessary	764.37 FS	*- FS
25	1		*FLAT CONTACT HOUSING H/LAMP WIRE HOUSING	Not Necessary	21.07 FS	*- FS
26	1		*FRT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
27	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS
28	1		*REVERSE SENSOR	Not Necessary	400.00 FS	*- FS
29	1		*REFRIGERANT CONDENSER WIT	Bent	757.30 FS	*757.30 FS
30	1		*SEAL RING	Necessary	5.95 FS	*5.95 FS
31	1		*SEAL RING	Necessary	5.74 FS	*5.74 FS
32	1		*OIL FOR REFRIGERANT COMPR (0.1)	Necessary	37.04 FS	*37.04 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	7,961.51	3,097.18
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR REAR	New	2,520.00	840.00
2	SPRAY PAINT REAR	New	2,400.00	800.00
3	LABOUR FRT	New	2,520.00	1,260.00
4	SPRAY PAINT FRT	New	2,400.00	800.00
5	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	360.00	360.00
6	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
7	LEAKED CHECK ,VACUUM & REGAS	New	420.00	420.00
8	A/C GAS	New	60.00	60.00
9	LABOUR TO REPLACED CONDENSER	New	420.00	0.00
Gross Labour Cost (\$\$)			11,580.00	5,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >