

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21005617/R1QF3E2-1

Date: 03/08/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : GBK9035J **Insured Vehicle No :** SLW1898G
Date of Loss: 03/05/2021 Nature of Claim: TP Claim No: MFL2021D0001937

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK9035J**
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KDB065371
Reg. Date: 07/01/2021 (Man. Year: 2020) Chassis No: JTFHT02P100250990
Colour: White Odometer: 8091 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,279.36	3,005.11	2,274.25	43.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,050.00	1,390.00	56.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,719.36	4,055.11	3,664.25	47.47
Approved Total (Overridden) (S\$)		3,250.00		
Nett Amount (S\$)	7,719.36	3,250.00	4,469.36	57.90

INSPECTION

Date of Assignment: 01/07/2021
Date Inspected: 10/05/2021 Inspected At: Kok Wang Car Grooming (HQ)
1 SOON LEE STREET #06-40 PIONEER CENTRE
Singapore 627605
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2021)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK9035J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S HEADLAMP	Damaged	960.80 FL	*750.00 FL
2	1		*FRONT BUMPER	Damaged	862.16 FL	*510.00 FL
3	1		*FRONT BUMPER O/S SIDE BRACKET	Not Necessary	89.30 FL	*- FL
4	1		*FRONT O/S DOOR	Damaged	1,670.00 FL	*1,670.00 FL
5	1		*FRONT O/S DOOR CHECKER	Damaged	35.80 FL	*35.80 FL
6	2		*FRONT O/S DOOR HINGES	Damaged	155.96 FL	*155.96 FL
7	1		*FRONT O/S DOOR INNER BOARD	Damaged	897.50 FL	*615.00 FL
8	1		*FRONT O/S DOOR LOCK	Not Necessary	272.50 FL	*- FL
9	1		*FRONT O/S DOOR OUTER HANDLE	Not Necessary	163.50 FL	*- FL
10	1		*FRONT O/S DOOR SPEAKER	Not Necessary	185.00 FL	*- FL
11	1		*FRONT O/S DOOR PILLAR	Repair	729.00 FL	*- FL
12	1		*FRONT O/S DOOR REGULATOR	Not Necessary	211.36 FL	*- FL
13	1		*FRONT O/S DOOR REGULATOR MOTOR	Not Necessary	489.55 FL	*- FL
14	1		*FRONT O/S DOOR RUBBER	Necessary	190.05 FL	*190.05 FL
15	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
16	1		*FRONT O/S DOOR LETTERING	Necessary	45.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,007.48	3,986.81
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,728.12	981.70
Total Parts (\$\$)	5,279.36	3,005.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING, LIGHTING AND RESETTNG HEADLAMPS FOCUSING	New	80.00	30.00
2	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	180.00	80.00
3	TO APPLY UNDERCOATINNG ON REPAIRED AND REPLACED PANEL	New	100.00	40.00
4	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,080.00	400.00
5	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
Gross Labour Cost (\$\$)			2,440.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >