



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 3696C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOX OPEN DOOR LH	DISTORTED	3,800.00	1,600.00
1	REAR BOX OPEN DOOR STICKER '60KM/H'	NECESSARY	30.00	10.00
2	REAR DOOR OPEN DOOR HINGE @\$250.00	NOT NECESSARY	500.00	-
1	REAR BOX COMPANY STICKER	NECESSARY	1,800.00	400.00
			6,130.00	2,010.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOX OPEN DOOR ALUMINIUM PANEL LH (SN)	DENTED	600.00	300.00
			600.00	300.00
	<u>LABOUR</u>			
	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK.		1,600.00	250.00
	TO PUTTY, SPRAY PAINT, POLISH WAX.		1,600.00	400.00
	TO SPRAY TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING, BULB CHECKING.	NOT NECESSARY	80.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			3,710.00	650.00
	GRAND TOTAL		10,440.00	2,960.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00

Report Ref No. CS/SMR21007231/Auf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.