

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21007235/Etce2	
	8 SHENTON WAY TOWERSINGAPOR	-	Date:	15/07/2021	
	ATTN: CHAN KIAN	CHUAN	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 56P	Veh. Inspected	FBA 6154X	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S1M03CN4	Excess (\$)	0.00	
	Assign From	CHAN KIAN CHUAN	Assign Date	01/07/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CB400S	c.c	399	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	JH2NC39985M100323	Colour	WHITE	
	Odometer	222460 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	120/60Z R17	MICHELIN	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	160/60Z R17	MICHELIN	4 mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR O/S PORTION.			
5.	5. General Information				
	Accident Date	24/06/2021	Inspect Date / Time	01/07/2021 (04:00 PM)	
	Survey held at EQUIPMENT EXTREME				
	BLK 4001 DEPOT ROAD DEPOT LANE #01-10 SINGAPORE 109755				
5a.	. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair					
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			

Report Ref No. CS3/ASM21007235/Etce2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser